## Bill Of Materials for Bode Analyzer

**Design Title** Bode Analyzer

Author Paulo Miyoshi Pecegueiro

**Document Number** TCC prj1

Revision 1

Design CreatedSunday, November 27, 2022Design Last ModifiedMonday, November 13, 2023

**Total Parts In Design** 155

61 Cap							
<u>Quantity</u>	<u>References</u>	<u>Value</u>	Stock Code	<u>Unit</u> <u>Cost</u>	Extended	PCB Package	
21	C1,C2,C5,C6,C10,C13,C14, C15,C16,C17,C18,C19,C22, C23,C26,C43,C46,C50,C51, C55,C58	100n	C14663	\$0.00	False	0603_CAP	
12	C3,C8,C11,C24,C28,C37, C41,C47,C48,C49,C53,C56	47u	C96123	\$0.08	False	CAPC3216X140	
13	C4, C7, C9, C12, C25, C29, C38, C40, C42, C45, C52, C54, C57	1.0u	C15849	\$0.00	False	CAPC1608X87	
2	C20,C21	12pF	C1547	\$0.00	False	CAPC1005X55	
2	C27,C36	220u	C136294	\$0.30	True	CAPAE830X1080N	
2	C30,C44	2.2u	C23630	\$0.02	False	CAPC3216X140	
4	C31,C32,C33,C34	12pf	C38523	\$0.01	False	CAPC1608X87	
1	C35	22U	C250970	\$0.18	True	CAPPRD250W50D630H1270	
4 Sub-totals	C59,C60,C61,C62	2n2	C1604	\$0.00 \$1.91	False	0603_CAP	
66 Resi				*			
	References	<u>Value</u>	Stock Code	<u>Unit</u> Cost	Extended	PCB Package	
2	R1,R2	5.1K	C23186	\$0.00	False	RESC1608X50A	
1	R3	0	C21189	\$0.00	False	RESC1608X50A	
10	R4,R39,R40,R41,R42,R43, R44,R45,R46,R47	56K	C23206	\$0.00	False	RESC1608X50A	
1	R5	120	C25079	\$0.00	False	RESC1005X40	
10	R6,R7,R55,R56,R57,R58, R63,R64,R65,R66	1.2K	C22765	\$0.00	False	RESC1608X50A	
38	R8,R9,R10,R11,R12,R13, R14,R15,R16,R17,R18,R19, R20,R21,R22,R23,R24,R25, R26,R27,R28,R29,R30,R31, R32,R33,R34,R35,R36,R37, R38,R48,R49,R50,R51,R52, R53,R54	51.0	C23197	\$0.00	False	RESC1608X50A	
4 Sub-totals	R59,R60,R61,R62	0.1	C21189	\$0.00 \$0.06	False	RESC1608X50A	
7 Integrated Circuits							
_	References	<u>Value</u>	Stock Code	<u>Unit</u> <u>Cost</u>	Extended	PCB Package	
1	U1	STM32G474VET6TR	C431632	\$7.34	True	QFP50P1600X1600X160-100N	
2	U2,U3	LP5907MFX-3	C80670	\$0.19	True	SOT95P280X145-5N	
1	U4	W25Q128JVSIQ	C97521	\$0.59	True	SOIC127P790X216-8N	
2	U5,U6	LMV358A	C63813	\$0.15	True	SOIC127P600X175-8	
1	U8	ADS131M04IPWR	C2862562	\$2.70	True	SOP65P640X120-20N	
Sub-totals	);			\$11.28			
4 Diode	es.						

Quantity	References	<u>Value</u>	Stock Code	<u>Unit</u> <u>Cost</u>	Extended	PCB Package			
1	D1	SQV05C	C490620	\$0.19	True	SOT95P280X145-5N			
1	D2	SS34	C8678	\$0.03	False	DO214			
2 Sub-totals	D3,D4 s:	BAV99	C2500	\$0.01 \$0.24	False	SOT23			
17 Miscellaneous									
<u>Quantity</u>	<u>References</u>	<u>Value</u>	Stock Code	<u>Unit</u> <u>Cost</u>	<u>Extended</u>	PCB Package			
3	B1,B2,B3	GZ2012D601TF	C1015	\$0.01	False	BEADC2012X105N			
2	BOOT, RESET	SKRKAEE020	C455280	\$0.05	True	SKRKAEE020			
2	DEBUG, STLINK	CONN-SIL4	MISS			CONN-SIL4-HIGH ANGLE			
2	IN,OUT	BNC	MISS			BNC			
2	J1,J2	CONN-SIL4	MISS			CONN-SIL4			
1	LCD1	ATK-4.3	MISS			4.3 TFT L35510 - NO DISPLAY			
2	LED1,LED2	SML0805-AG3K-TR	C84256	\$0.01	False	0805			
1	SW1	SK-3296S-01-L3	C319019	\$0.07	True	SK3296S01L3			
1	USB	TYPE-C-31-M-12	C165948	\$0.21	True	TYPE-C-31-M-12			
1	X1	3TJ481920NYLBC	C2898996	\$0.21	True	YSX321SL			
Sub-totals: \$0.64									

Totals: \$14.14

## **MIYOSHI TECNOLOGIA LTDA**

Monday, November 13, 2023 1:59:08 AM