

Vehicle Visual Inspection Report

Inspection Result	FAILED
Damage Detected	True
Damage Type	crack
Location	left_door
Severity	high
Confidence	51.8%
Repair Recommendation	Repair or replace cracked component
Timestamp	2026-06-18T04:35:42.917654+00:00

Annotated Image

