Feuille1

UPPY pin mapping Stage :alpha V0.1



Stage :alpha V0.1 **MC Hobby SPRL** shop.mchobby.be

Stage :aipna		V0.1		MC Hobby SPRL Snop		snop.mcnoppy.be						
PyBoard		Feather (M0)			UEXT		Connect Everything (NCD)			Gr	Gr	
Pin	Feature	Pin	Pin Alternate	Feature	Pin	Pin Alternate	Feature	Pin	Pin Alternate	Feature	Pin	
X6	ADC, DAC	A0	14	DAC								
X19	ADC,C0	A1	15	shielded ADC								
X20	ADC,C1	A2	16	shielded ADC								
X21	ADC,C2	A3	17	shielded ADC								
X22	ADC,C3	A4	18	shielded ADC								
X11	ADC	A5	19	ADC								
Y5	SPI(2) /SS				10	SSEL						
Y6	SPI(2) SCK	SCK	24		9	SCK	SPI					
Y8	SPI(2) MOSI	MOSI	23	SPI	8	MOSI	SPI					
Y7	SPI(2) MISO	MISO	22		7	MISO						
Y1	UART(6) RX	RX	0	Coriol								
Y2	UART(6) TX	TX	1	Serial								
Y10	12C(2) SDA	SDA	20	I2C	6	SDA	I2C		2 SDA 5V	I2C OUT		
Y9	12C(2) SCL	SCL	21	4.7K pull-up To 3.3V	5	SCL	4.7K pull-up To 3.3V		1 SCL 5V	CE Connector 5V level shifting !!		
X1	Servo	5~		PWM (+Servo)								
X12	PWM,ADC	6		PWM (+extra ADC)								
X2	Servo	9~		PWM (+Servo)								
X3	Servo	10~		PWM (+Servo)								
X4	Servo	11~		PWM (+Servo)								
X7	Servo	12		PWM								
X8	PWM	13		PWM. NO LED Wir	ed!							
X9	12C(1) SCL, U	ART(1)	(TX), PWM		3	TXD	Use a different serial	1				
X10	I2C(1) SDA, U				4	RXD	port than Feather.					
Y11	PWM,ADC	NEOPIX	(11	No Neopixel wired!								

Powering									
V+	3.6 to 16V Max 5V advised!	USB	VUSB	May be higher than 5V !!		3	V+	May be higher than 5V !!	
RST		EN		will deactivate the pyboard MCU					

Feuille1

RST	RST								
3.3V	BAT	VBAT	Not battery! 3.3V only	1	3.3V				١
3.3V	3.3V		250mA max instead of 400mA						١
GND	GND			2	GND	4	GND		l

Revision History

March 3, 2019 Initial setup

ove Connector Pin Alternate Feature							

Feu	ıille	е1
	4111	\sim \pm