

# STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-06 18:41:45 | Method: Deep Learning Classification



| Metric Parameter    | Inspection Value |
|---------------------|------------------|
| Class Diagnosis     | PAVEMENT_CRACKED |
| Structure Element   | Pavement         |
| Condition Status    | DAMAGED          |
| Confidence Score    | 61.50%           |
| Severity Assessment | Severe           |
| Safety Factor       | 0.40             |
| Camera Distance     | 2000 mm          |
| Focal Length        | 800 px           |

|                    |           |
|--------------------|-----------|
| Measured Avg Width | 9.321 mm  |
| Measured Max Width | 17.984 mm |
| Crack Length       | 337.5 mm  |
| Crack Orientation  | 178 deg   |

***Engineering Recommendation:***

PAVEMENT EVALUATION: Repair required within 30 days. Restrict load if near critical members. Engineer review recommended. (Critical Limit: 6.0mm | Allowable Max: 12.0mm) | Measured: 9.32mm