

STRUCTURAL HEALTH MONITORING REPORT

Timestamp: 2026-09-06 18:39:05 | Method: Deep Learning Classification



Metric Parameter	Inspection Value
Class Diagnosis	PAVEMENT_CRACKED
Structure Element	Pavement
Condition Status	DAMAGED
Confidence Score	76.95%
Severity Assessment	Severe
Safety Factor	0.40
Camera Distance	2000 mm
Focal Length	800 px

Measured Avg Width	11.291 mm
Measured Max Width	21.969 mm
Crack Length	210.0 mm
Crack Orientation	80 deg

Engineering Recommendation:

PAVEMENT EVALUATION: Repair required within 30 days. Restrict load if near critical members. Engineer review recommended. (Critical Limit: 6.0mm | Allowable Max: 12.0mm) | Measured: 11.29mm