
1
0.5
0
-0.5
-1
Imaginary part
(a)
-1
0
1
2
3
Real part
Integrator
Motor + filter
Bar mode
Zero
Non-min. phase zero