

Ref. Fabricante	Descrição
B0GYD9NZLV	RC Rally Tires pneus de corrida todo-o-terreno resistente
B0DP3H7R8K	BreadBoard
B0D8T3N7HQ	ESP 32
B0C84VLLC9	4 peças L298N Placa de controlador de acionamento de motor
B0D1K85KQG	Módulo ultrassônico
B07MH3Z9JH	OVONIC 3S Lipo Battery 50C 5200 mAh 11,1 V Lipo Battery
B0FS1FN2H4	2 Peças Módulo Conversor Buck DC-DC, Módulo de Alimentação
B0B15JP8DV	motor de engrenagem redução de microvelocidade de alto torque
B07QM1WS2J	3 pares de conectores de tomada em T fêmea e macho com cabo de silicone
IRFF	Módulo Sensor Infravermelho Obstáculo
010-1510	Interruptor On OF
095-6226	Kit Jumpers

Categoria	Quant.	Preço un.	Sub-total	Distribuidor
Pneus	4	€4,96	€19,82	Amazon
Eletrónica	2	€3,31	€13,22	Amazon
Eletrónica	1	€5,57	€5,57	Amazon
Microcontrolador	2	€6,10	€12,19	Amazon
Sensor	3	€3,75	€11,25	Amazon
Bateria	1	€32,52	€32,52	Amazon
Energia	1	€6,09	€6,09	Amazon
Motor	4	€12,15	€48,60	Amazon
Conectores	1	€8,12	€8,12	Amazon
Sensor	2	€0,87	€1,74	AliExpress
Interruptor	1	€0,80	€0,80	Mauser
Kit	1	€3,20	€3,20	Mauser
Sub-Total			€143,30	

URL

https://www.amazon.es/-/pt/gp/product/B0GYD9NZLV/ref=ox_sc_act_title_1?smid=A2ZS2
https://www.amazon.es/-/pt/dp/B0DP3H7R8K/ref=sr_1_21?crid=1FU3TG
https://www.amazon.es/-/pt/dp/B0D8T3N7HQ/ref=sr_1_13?dib=eyJ2ljo
https://www.amazon.es/-/pt/gp/product/B0C84VLLC9/ref=ox_sc_act_title
https://www.amazon.es/-/pt/gp/product/B0D1K85KQG/ref=ox_sc_act_title
https://www.amazon.es/-/pt/gp/product/B07MH3Z9JH/ref=ox_sc_act_title
https://www.amazon.es/-/pt/gp/product/B0FS1FN2H4/ref=ox_sc_act_title
https://www.amazon.es/dp/B0B15JP8DV/ref=mp_s_a_1_20?crid=12H4G
https://www.amazon.es/-/pt/gp/product/B07QM1WS2J/ref=ox_sc_act_title
<https://pt.aliexpress.com/item/1005004089616586.html>
<https://mauser.pt/010-1510/interruptor-basculante-redondo-2-posicoes->
<https://mauser.pt/095-6226/keyestudio-ks0325-conjunto-de-120-cabos-c>

[i7AYZF9Y&dib=eyJ2ljojMSJ9.CAA01D4NlqfkzJX21Zj14rgAl9defdziD1sJCfPg1oMjdOwWvOtV0iZmDQMSJ9.wXum05Bh34pgNYsdkUvPvXQ_2VFG64iPe8xormACGeK7qTJSaZq6Xh4cjinpHygE1w5kA-MPvh](#)

[BHFWRZUR&dib=eyJ2ljojMSJ9.ixPISCrFr2D-yQBhliMNVetFCBJ4_npzmAlHyaRkt71lgHvlt8tO5Q_lqx](#)

[2BGMuireDYfHdmLtlQf-JqbA7ktd4P60wn2lZyh-AhTp0FMOgbRwFG8TYd9RR2qKveRJWMchayC6W
2ST3lLFOp0sWcwfvoqMpvDL-jAR6fjty4Hu7RSWZcLz8tirNMWWvSUBqXvX83Xn-qC5n2HNCm11ydf](#)

[8fUvxZ0 D93P554LIEPOAH8-u7l8KB3iMASv2HEgF CyiX4uG0H7qzpb0oWHATExxV5K Axl0RB1ZJF-](#)

[FRmGgdC- eWRCdDrBE36xLopIUWIRWAFVT3a8h1DPUjTA1qONjYIF4-50bLYs9ITZOOhMPjJVH72HL
?JqtmoVQuDaxndF 4TLdAxjVoSLNCLOWTdwZkWRH4F9aiRyqyeRN97rVFB2449ltAipyAUopZDRJZI0N](#)

[.NzjjYtgbTkO8nkG8fKOPASrsqLP0BV73JRUdaMP1iCNTtKxyqjt504NrBELygp2FTP4DmEMY1h0WpLnC](#)

[.Vteu IAUS8V-1Su5OcScbtckjlv6Zj-DUkz89YkGaEOq3bE36TFmcd7WrTAV-KSxYpv7PNd2eo792wJQf
/srWB1ln4GXUEf3yDe-e 1c2CgDr-31 4spQt78SQ45jMVxIMHvuS6T MDevswvC5b66Sk.5cuD1SQ9](#)

[jrCF4XBhb jn4ZqQGiGD-jrLIOHUUgJZ7xHN5FVi2hilE3ZW1LdB9YON4170MBsE83p7C9sdV- o49HM](#)

[168xvk.iJelv-4CzuXF9fTklvF8v5S-9rrX9uUCDttHHNt35Ho&dib tag=se&keywords=breadboard&qid=taC BKocZ9EJcH5sfP64axYjDQeHJWI3qH8&dib tag=se&keywords=esp%2B32&qid=1777457843&s](#)

[U.5fSTyDpTW4I--Uv6hVI6uleSMv8jxTXUqsFrnGTE4L0&dib tag=se&keywords=Motor%2BDC%2B12](#)

!%2BV%2Bmotor%2Bde%2Bred%C3%A7%C3%A3o%2Bde%2Bengrenagens%2Bel%C3%A9tricas%2

[!Bde%2Balto%2Btorque%2B15&qid=1779310873&refinements=p_85%3A20930978031&rnid=209](https://doi.org/10.1101/177931)

[30977031&rps=1&s=industrial&sprefix=motor%2Bdc%2B12%2Bv%2Bmotor%2Bde%2Bred%C3%](#)

[A7%C3%A3o%2Bde%2Bengrenagens%2Bel%C3%A9tricas%2Bde%2Balto%2Btorque%2B15%2B%2C](#)

[industrial%2C132&sr=1-20&th=1](#)