

ADCOLE Model 911 SN-8609			Scania Brazil Camshaft Measurement					SCANIA																	
Date: 18/mar/26 Time: 13:42:25 Oper.: teste			Datatable: 1832910.DAT Program: 1832910_120.S01 ReportNo: rept0063.CAM					Filter Journal: 50 upr (Gauss) Cam: 50 upr (Gauss)																	
Part : XPI5 1.832.910 Serial: 2345665433					Operação: OP_120 Máquina : Landis_B			Razao :Teste Coment:teste																	
Journals																									
Max-Dia		Min-Dia		Meas-Dia		Diameter Error		Round ness		Ecc--Ref Gage		Axis Part		Runout											
Nom:				84,953																					
Tol:								,010				,070		,100											
A	84,983	84,968	84,954#	,001#	,001	,020	,000	,001																	
B	84,983	84,968	84,943#	-,010#	,001	,011	,005	,011																	
C	84,983	84,968	84,937#	-,016#	,002	,008	,005	,011																	
D	84,983	84,968	84,947#	-,007#	,001	,011	,005	,011																	
E	84,983	84,968	84,934#	-,019#	,001	,011	,004	,009																	
F	84,983	84,968	84,951#	-,002#	,001	,009	,000	,001																	
Cams																									
Angle of cam number 1 to reference (127,650 -- 128,150) 127,966																									
		Angle Error Pino		Angle Error Cam1		-----Base Circle----- Radius Error 31,380 32,000		Runout		Velocity Error		-----Lift Error----- Nose Meas Angle		Ramp Meas Angle		-----Lift Dif----- Nose Meas Angle		Ramp Meas Angle		Center Dev.		Taper Error		Parallelism	
Nom:																									
Tol:		,250		,125		,100		,040		,010		,100		,050		,010		,010		,0100		,020		,015	
		-,250		-,125		-,100		-,040		-,010		-,100		-,050		-,010		-,010		-,0030		,020		-,015	
1	A1 EXH	,066	,000	,003	,004	,000	,026	140	,033	136	-,002	140	-,003	241	,0001	,000	,001								
2	I1 INT	,057	-,009	,004	,007	,000	,022	144	,030	139	-,002	144	-,002	143	,0015	,005	,002								
3	A2 EXH	,060	-,006	,006	,004	,000	,021	140	,028	136	-,002	140	-,003	241	,0006	,002	,001								
4	I2 INT	,060	-,006	,006	,006	-,001	,019	144	,024	140	-,002	144	,002	127	,0013	,007	,001								
5	A3 EXH	,065	-,001	,007	,002	,000	,017	140	,021	136	-,001	140	-,002	241	,0002	,003	,001								
6	I3 INT	,061	-,005	,002	,003	,000	,018	144	,022	140	-,001	144	,002	128	,0003	,005	,001								
7	A4 EXH	,067	,001	,001	,001	,000	,019	140	,024	136	-,001	140	-,002	242	,0002	,001	,004								
8	I4 INT	,051	-,015	,003	,003	,000	,016	144	,021	140	-,002	177	,002	128	,0004	,005	,004								
9	A5 EXH	,051	-,015	-,002	,001	,000	,017	140	,022	136	-,002	140	-,003	242	,0011	,003	,004								
10	I5 INT	,055	-,011	-,005	,003	,000	,020	144	,024	140	,002	181	,002	127	-,0003	,005	,004								
Check report for flags.																									

Message # 022 is for a printer form feed

Remove 4.5" Follower Tip Install 2"

Journal Roundness

Base circle radius reduced from 1.2786 to 1.2706 inches.

0

1

2

3

4