










C39:
 $X_c = 1/2 \pi f C$
 $\Rightarrow C = 1/2 \pi f X_c$
 $C = 1/(2 \pi \cdot 25\text{MHz} \cdot 120 \text{ ohm})$

L8:
 $X_l = 2 \pi f L$
 $L = X_l / 2 \pi f$
 $L = 120\text{ohm} / (2 \pi \cdot 25\text{MHz})$

Sheet: /freq_converter/
 File: f_conv.kicad_sch

Title: Frequency converter

Size: A4 Date: 2026-02-24

KiCad E.D.A. 10.0.1

Rev: 2.4

Id: 4/4