PWM	1/0	1H	2L	ЗН	4L	Motor
(1)	0	V			V	->
(0)	1		V	V		<
(1)	1	V		V		
(0)	0		V		V	

