
Cumulative control rods position $h_{cr}(t)$
h_{cr} (withdrawn steps)
Time (h)
Integral cost function
$\int_0^T \ell(x(t), u(t))dt$
Time (h)
Power axial offset deviation $\Delta AO(P(t))$
Safety Limit
$AO(P(t)) - AO_{P,ref}$ (%NP)
Time (h)
Core Power $\sum_{i=1}^{n_z} P_i(t)$
$\sum_{i=1}^{n_z} P_i(t)$ (%NP)
Time (h)
Boron concentration $C_b(t)$
C_b (ppm)
Time (h)
Xenon relative density
$\frac{\sum_{i=1}^{n_z} X_i(t)}{\sum_{i=1}^{n_z} X_{i,eq}}$ (at/ang^3)
Time (h)
Proposed method
Behavior Cloning
Shift-Init - Change w
Shift-Init - Change J
Cold-start