

Offer to Purchase

	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

Page 1 of 12

Offer Presented To:

JOSEPH KODOS 26075 Clear St Harrison Township MI 48045 US

Joseph Kodos

Phone: 586-612-2518

Fax:

perfectfireiii@gmail.com

Offer Created By Brian Klimp Ext:824

Radwell International, Inc. 1 Millennium Drive Willingboro NJ 08046 US

Please note: Radwell will pay the shipping cost. We would prefer that you ship using our UPS account number, which we can provide should you accept this offer. If truck freight is required due to the size of the shipment, please contact us to arrange pick up.

Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
2	1745-C1		
	ALLEN BRADLEY	Each	
RQAUS1	Discontinued by manufacturer 04/30/2014, ,CABLE REPLACEMENT FOR SLC100/SLC150 1.8M LENGTH,Replacement Interconnect Cable for SLC 100 and SLC 150 processors		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be miss	ing.
Vendor's part nu	umber is 1745-C1		
3	1745-C2		
	ALLEN BRADLEY	Each	
RQAUS1	Discontinued by manufacturer 04/30/2014, SLC 100 Interconnect Cable for connecting Expansion Units to SLC 100 CPU, 10-Pin to 10-Pin, 18.5-inch (47 cm) Length, 70V Max, Twisted Pair, ,CABLE EXPANSION, SLC INTERCONNECT RIBBON		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be miss	ing.
Vendor's part nu	umber is 1745-C2		
4	1745-C3		
	ALLEN BRADLEY	Each	
RQAUS1	Discontinued by manufacturer 04/30/2014, SLC-100 Processor-to-Expansion Cable, 18.5-inch (47cm) 70V max, Twisted Pair, , CABLE, 18.5INCH, PROCESSOR TO EXPANSION		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be miss	ing.
Vendor's part nu	umber is 1745-C3		
2	1745-E151		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED BY MANUFACTURER, EXPANSION UNIT, SLC-150, FOR PROGRAMMABLE CONTROLLER, 20 EXTERNAL I/O INPUT CIRCUITS (85-132V AC 50/60HZ CURRENT SINKING); 12 EXTERNAL I/O OUTPUT CIRCUITS, ,EXPANSION UNIT,SLC150,85-132VAC,50/60HZ		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be miss	ing.

Used in working condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessory items may be missing. Vendor's part number is 1745-E151



	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Rid ID:	433421

			Page 2 of 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes	l .	
4	1745-LP151		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED BY MANUFACTURER, PLC MODULE, LC 150, 20INPUT SINKING, 10OUTPUT, 2OUTPUT RELAY, (2) 10-250VAC /10-125VDC HARD CONTACT RELAY OUTPUTS, POWER: 85-132/170-265VAC 50/60HZ,(10) 85-265 VAC TRIAC OUTPUTS, NUMBER OF I/O: (20) 85-132VAC		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missir	ng.
Vendor's part nu	mber is 1745-LP151		
3	1745-M1		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY, 1745-M1, 1745M1, MEMORY MODULE, 1200 WORD MAX		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missir	ng.
Vendor's part nu	mber is 1745-M1		
2	1745-TCAT		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY, 1745-TCAT, 1745TCAT,INTERFACE, PROGRAMMING MODULE FOR SLC100/150		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missir	ng.
Vendor's part nu	mber is 1745-TCAT		
14	1746-IA16		
	ALLEN BRADLEY	Each	
RQAUS1	INPUT MODULE, 16POINT, DIGITAL, SLC500, 85-132VAC, 47-63HZ		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missir	ng.
Vendor's part nu	mber is 1746-IA16		
4	1746-IV16		
	ALLEN BRADLEY	Each	
RQAUS1	INPUT MODULE, 16POINT, 10-30VDC, SOURCE		
Used in working	$condition, item \ is \ in \ resalable \ condition, \ without \ severe \ cosmetic \ damage, \ some \ OEM \ supplied \ accessors \ damage.$	y items may be missir	ng.
Lines 7 and 12 v	vere combined. Vendor's part number is 1746-IV16		
8	1746-NI4		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY ,1746-NI4 ,1746NI4 ,INPUT MODULE, 4 POINT, ANALOG, 20 AMP, 10 VDC, SLC500,		
	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missir	ng.
Vendor's part nu	mber is 1746-NI4		
1	1746-NIO4V		
	ALLEN BRADLEY	Each	
RQAUS1	I/O MODULE, 2IN, 2OUT, ANALOG, SLC 500, HIGH RESOLUTION COMBINATION MODULE, 2 ANALOG INPUTS, 2 ANALOG VOLTAGE OUTPUTS, 24VDC, 115MA		
_	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	•	ng.
Part Number 174	46-O4V seemed to be incomplete. The above part number is a possible match. Vendor's part number is	1746-O4V	



Offer Date:	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

		Page	3 of 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
3	1746-OA16		
	ALLEN BRADLEY	Each	
RQAUS1	OUTPUT MODULE, 16POINT, 120/240VAC, SLC500		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1746-OA16		
2	1746-OB32		
	ALLEN BRADLEY	Each	
RQAUS1	OUTPUT MODULE, 32POINT, 5/50 VDC, 0.5/0.25 AMPS, 30/60 DEG C		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1746-OB32		
6	1746-OW16		
	ALLEN BRADLEY	Each	
RQAUS1	OUTPUT MODULE, 16POINT, RELAY, 250VAC, 125VDC, SLC500		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1746-OW16		
1	1746-OW8		
	ALLEN BRADLEY	Each	
RQAUS1	OUTPUT MODULE, 8POINT, RELAY, 125VDC, 5-265VAC, 50/60HZ, SLC500		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1746-OW8		
12	1747-AIC		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY, 1747-AIC, 1747AIC, LINK COUPLER, FOR PROGRAMMABLE CONTROLLER, DH—485 NETWORK, 6 POSITION, 24 VDC		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1747-AIC		
1	1747-KE		
	ALLEN BRADLEY	Each	
RQAUS1	discontinued by manufacturer, Communications Interface Module, (1) DH-485, (1) DF1, (1) Configuration DF1 and Configuration ports, INTERFACE MODULE, .0415AMP, 5-24VDC, 3PORT		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Part Number 174	46-KE seemed to be incomplete. The above part number is a possible match. Vendor's part number is	1746-KE	
2	1747-L514		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED AS OF 01/31/2017, CPU MODULE, 4K RAM MEMORY, DH-485, SLC5/01		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be missing.	
Vendor's part nu	mber is 1747-l 514		



	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Rid ID:	433421

			Page 4 of 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
2	1747-L524		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED BY MANUFACTURER, PROCESSOR MODULE, 4K MEMORY, DH485, COMMUNICATION		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing	j .
Vendor's part nu	mber is 1747-L524		
6	1747-L531		
	ALLEN BRADLEY	Each	
RQAUS1	CPU MODULE, SLC5/03, 8K USER MEMORY		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing] .
Vendor's part nu	mber is 1747-L531		
2	1747-L551		
	ALLEN BRADLEY	Each	
RQAUS1	SLC 5/05 Controller, 16K, Ethernet & RS-232. User Memory, Max: 16K words total (12K words for data or prog., 4K words for data only); Number of I/O: 4096 in + 4096 out absolute maximum; Local Analog I/O, Max: 480; Program Scan Time/Kword: 0.9 ms (typ)		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing	J .
Vendor's part nu	mber is 1747-L551		
2	1747-PIC		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED AS OF 12/31/2015, CONVERTER INTERFACE, W/RS232 TO DH485 CABLE		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing] .
Vendor's part nu	mber is 1747-PIC		
1	1747-SDN		
	ALLEN BRADLEY	Each	
RQAUS1	DISCONTINUED BY MANUFACTURER, SCANNER MODULE, DEVICENET, 5-24VDC, 90-500MA		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing	
Part Number 17	46-SDN seemed to be incomplete. The above part number is a possible match. Vendor's part number is	1746-SDN	
3	1756-A10		
	ALLEN BRADLEY	Each	
RQAUS1	PLC RACK, CONTROLLOGIX,10 SLOT, 20 X 30 X 8 INCH		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing].
Vendor's part nu	mber is 1756-A10		
2	1756-A7		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY, 1756-A7, 1756A7, CONTROL RACK, 7SLOT, 20X24X8INCH		
	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	y items may be missing].
Vendor's part nu	mber is 1756-A7		



Offer to Purchase

	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Rid ID:	433421

Page 5 of 12

			rage 3 01 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
2	1791-16A0		
	ALLEN BRADLEY	Each	
RQAUS1	ALLEN BRADLEY ,1791-16A0 ,179116A0 , BLOCK I/O INPUT MODULE, 16 IN, 120 VAC		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	ry items may be miss	sing.
Vendor's part nu	mber is 1791-16A0		
1	1791-N4C2		
	ALLEN BRADLEY	Each	
RQAUS1	Discontinued by manufacturer 06/30/2015, BLOCK I/O, 120V AC, 6 POINT ANALOG MODULE, Block I/O Analog Input/Output Combination Module, (4) Analog Current/Voltage Inputs and (2) Analog Current/Voltage Outputs, 120V AC Supply Power		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accessor	ry items may be miss	ing.
Vendor's part nu	mber is 1791-N4C2		
2	802T-HP		
	ALLEN BRADLEY	Each	
RQANS2	LIMIT SWITCH, SPRING RETURN, 10AMP, 600VAC, 720VA		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	m has never been
Part Number 802	2-HP seemed to be incomplete. The above part number is a possible match. Vendor's part number is 80)2-HP	
14	802T-W17		
	ALLEN BRADLEY	Each	
RQANS2	ALLEN BRADLEY, 802T-W17, 802TW17, ROLLER LEVER, 4IN RADIUS, ADJUSTABLE, 1.19-4IN, NYLON, FOR LIMIT SWITCH		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	m has never been
Vendor's part nu	mber is 802T-W17		
3	802T-W2A		
	ALLEN BRADLEY	Each	
RQANS2	ROLLER LEVER, ADJUSTABLE, NYLON, 1.5IN		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	m has never been
Vendor's part nu	mber is 802T-W2A		
4	650-2384-010		
	ALTRA INDUSTRIAL MOTION	Each	
RQANS2	KIN-E40NS/004-KL2		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	m has never been
Vendor's part nu	mber is 650-2384-010		



Vendor's part number is SM2A31RL

Phone: 609.288.9393 Fax: 609.288.9414

Offer to Purchase

Offer Date:	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

Page 6 of 12

Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
1	OTBA5QD		
	BANNER ENGINEERING	Each	
RQANS2	OTB SERIES: MOMENTARY ACTION TOUCH BUTTON W/BLACK F.C.; INPUT: 120V AC; UPPER HOUSING: POLYSULFONE; OUTPUT: E/M RELAY (SPDT); QUICK-DISCONNECT CONNECTOR		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	em has never been
Vendor's part nu	mber is OTBA5QD		
1	RX1		
	BANNER ENGINEERING	Each	
RQANS2	PHOTOELECTRIC SCANNER BLOCK 120VAC 50/60HZ		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	em has never been
Vendor's part nu	mber is RX1		
2	S30AW3FF200Q1		
	BANNER ENGINEERING	Each	
RQANS2	EZ-BEAM S30 SERIES: FIXED FIELD; RANGE: 200 MM; INPUT: 20-250 V AC; OUTPUT: SPST SOLID-STATE LIGHT OPERATE; MICRO 4-PIN INTEGRAL QD		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	em has never been
Vendor's part nu	mber is S30AW3FF200Q1		
1	SM2A312CV		
	BANNER ENGINEERING	Each	
RQANS2	MINI-BEAM: VISIBLE RED 650 NM CONVERGENT; FOCAL POINT: 16 MM; INPUT: 24-240V AC; OUTPUT: SPST SOLID-STATE 2-WIRE; 2 M (6.5 FT) CABLE		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	em has never been
Vendor's part nu	mber is SM2A312CV		
1	SM2A312D		
	BANNER ENGINEERING	Each	
RQANS2	(25965). MINI-BEAM: DIFFUSE; RANGE: 380 MM; INPUT: 24-240V AC; OUTPUT: SPST SOLID- STATE 2-WIRE; 2 M (6.5 FT) CABLE		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	em has never been
Vendor's part nu	mber is SM2A312D		
3	SM2A31RL		
	BANNER ENGINEERING	Each	
RQANS2	RECEIVER, MINI-BEAM, RANGE: 30M, INPUT: 24-240VAC, OUTPUT: SPST, SOLID-STATE 2-WIRE, 2M/6.5 FT CABLE, (26061)		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	iged cosmetically, ite	em has never been



Vendor's part number is 8036AC15NL2AAXX

Phone: 609.288.9393 Fax: 609.288.9414

Offer to Purchase

	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

Page 7 of 12

			raye / Oi 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
2	SM31E		
	BANNER ENGINEERING	Each	
RQANS2	EMITTER, MINI-BEAM, RANGE 3M, INPUT 10-30VDC, OUTPUT NOT APPLICABLE / NO OUTPUTS, 2M / 6.5FT CABLE		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	m has never been
Vendor's part nu	mber is SM31E		
5	SM31R		
	BANNER ENGINEERING	Each	
RQANS2	RECEIVER, MINI-BEAM, RANGE 3M, INPUT 10-30VDC, OUTPUT / BIPOLAR / 1NPN / 1PNP, 2M / 6.5FT CABLE		
used or installed	· · · · · · · · · · · · · · · · · · ·	ged cosmetically, ite	m has never been
Vendor's part nu	mber is SM31R		
3	LR38595/E46203		
	CROUZET	Each	
RQANS2	CROUZET ,GORDOS , I /O MODULE 30VDC, 60HZ,		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	m has never been
Vendor's part nu	mber is LR38595/E46203		
3	991.11F		
	DANAHER CONTROLS	Each	
RQANS2	TEMPERATURE CONTROLLER, THERMOCOUPLES / 2 WIRE, 1/16 DIN, 115 VAC, 50/60 HZ, 6 VA, 1 RELAY OUTPUT AT 5 AMPS, 250 VAC RESISTIVE, SPDT, 1 RELAY OUTPUT AT 3 AMPS, 250 VAC RESISTIVE, SPDT, DEGREES F		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	m has never been
Vendor's part nu	mber is 991.11F		
3	13108A-6517		
	EATON CORPORATION	Each	
RQANS2	EATON CORPORATION, 13108A-6517, 13108A6517, PROXIMITY SWITCH, 10-39VDC, 6INCH RANGE, 4WIRE, EATON COMET SERIES, 6 INCH PERFECT PROX, IR, DC, CABLE		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never been used or installed and is working.			m has never been
Part Number 131	08A6517 seemed to be incomplete. The above part number is a possible match. Vendor's part number	is 13108A6517	
1	8036AC15NL2AAXX		
	EFECTOR	Each	
RQANS2	PROXIMITY SWITCH 20-250V 45-65HZ 2WIRE		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	m has never been



KGE2008-FBOA-KG0001

	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Rid ID:	433421

			Page 8 of 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
1	IGA2005-ABOA/SL/LS-100AK/RT-IG0337		
	EFECTOR	Each	
RQANS2	EFECTOR ,IFM ,IGA2005-ABOA/SL/LS-100AK/RT-IG0337 ,IGA2005ABOASLLS100AKRTIG0337 ,INDUCTIVE SENSOR, WITH COMBINED AC/DC OUTPUT, STAGE TWO-WIRE TECHNOLOGY ,WIDE OPERATING TEMPERATURE RANGE, ROBUST METAL HOUSING FOR USE IN HARSH INDUSTRIAL ENVIRONMENTS		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been
Vendor's part nu	mber is IGA2005-ABOA/SL/LS-100AK/RT-IG0337		
1	IGB2005-AB0A/SL/LS-100AK-IG0350		
	EFECTOR	Each	
RQANS2	EFECTOR,IFM, IGB2005-AB0A/SL/LS-100AK- IG0350,IGB2005AB0ASLLS100AKIG0350,PROXIMITY SENSOR,INDUCTIVE,8MM,20- 250VAC/DC,350mA AC,100mA DC,		
used or installed	· ·	aged cosmetically, ite	em has never been
Vendor's part nu	mber is IGB2005-AB0A/SL/LS-100AK-IG0350		
15	IGK2012-ABOA/SL/LS100-AK RT-IG0345		
	EFECTOR	Each	
RQANS2	INDUCTIVE SENSOR, WITH COMBINED AC/DC OUTPUT AND TWO-WIRE TECHNOLOGY LONG SENSING RANGE FOR HIGH UPTIME WIDE OPERATING TEMPERATURE RANGE ROBUST METAL HOUSING FOR USE IN HARSH INDUSTRIAL ENVIRONMENTS WITH ROBUST 1/2" CONNECTOR		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been
Vendor's part nu	mber is IGK2012-ABOA/SL/LS100-AK RT-IG0345		
1	IM5042		
	EFECTOR	Each	
RQANS2	PROXIMITY SWITCH INDUCTIVE 10-55VDC 400MA 15MM		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been
Vendor's part nu	mber is IM5042		
6	KG-2008-ABOA-KG0002		
	EFECTOR	Each	
RQANS2	EFFECTOR,IFM,KG-2008-ABOA ,KG2008ABOA ,PROXIMITY SWITCH CAPACITIVE, 8MM RANGE,20-250VAC/DC,CABLE:2M		
used or installed	· ·	aged cosmetically, ite	em has never been
Vendor's part nu	mber is KG-2008-ABOA-KG0002		r
1	KG-2008-FRKG/KG5016		
	EFECTOR	Each	
RQANS2	EFECTOR, IFM, KG-2008-FRKG/KG5016, KG2008FRKGKG5016, PROXIMITY SENSOR, 2.5-8MM RANGE, 400MA, 10-55VDC		
used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working. The companies KG-2008-EPKG/KG5016	aged cosmetically, ite	em has never been
I Vandor's nort ou	mhar is KG-2008-ERKG/KG5016		



Vendor's part number is OSE-FBOA/T

Phone: 609.288.9393 Fax: 609.288.9414

Offer to Purchase

	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

Page 9 of 12

Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
	EFECTOR	Each	
RQANS2	PROXIMITY SWITCH CAPACITIVE		
used or installed		aged cosmetically, ite	em has never been
Vendor's part nu	mber is KGE2008-FBOA-KG0001		
3	KI2015-ABOW		
	EFECTOR	Each	
RQANS2	PROXIMITY SWITCH CAPACITIVE 500MA 20-250VAC		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been
Lines 35 and 45 is KI-2015-ABO	were combined. Part Number KI-2015-ABOW seemed to be incomplete. The above part number is a poly	ossible match. Vend	dor's part number
10	KIE2015-FBOA/NI-KI0024		
	EFECTOR	Each	
RQANS2	CAPACITIVE SENSOR, EASY SETTING OF THE SENSING RANGE VIA POTENTIOMETER WITH COMBINED AC/DC OUTPUT STAGE TWO-WIRE TECHNOLOGY HIGH NOISE IMMUNITY OUTPUT FUNCTION NORMALLY OPEN / NORMALLY CLOSED PROGRAMMABLE		
	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama	aged cosmetically, ite	m has never been
used or installed Part Number KII K10024	e and is working. E2015-FBOA/NI-K10024 seemed to be incomplete. The above part number is a possible match. Vendor	r's part number is KIE	E2015-FBOA/NI-
6	OAT-FKOA/LS500L -OA3500		
	EFECTOR	Each	
RQANS2	OAT-FKOA/LS500L -OA3500, EFECTOR 200 PHOTOELECTRIC SENSORS, LIGHT CURTAINS AND FIBERS		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been
Vendor's part nu	mber is OAT-FKOA/LS500L -OA3500		
3	OFB-FPKG/US-100-OF5027		
	EFECTOR	Each	
RQANS2	DIFFUSE REFLECTION SENSOR, INTUITIVE SETTING OF THE SENSITIVITY VIA POTENTIOMETER WITH FUNCTION CHECK OUTPUT TO SIGNAL SOILING OR MALADJUSTMENT ROBUST METAL HOUSING FOR USE IN HARSH INDUSTRIAL ENVIRONMENTS PROGRAMMABLE LIGHT-ON/DARK-ON MODE WITH VERY FOCU		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	m has never been
Vendor's part nu	imber is OFB-FPKG/US-100-OF5027		
1	OSE-FBOA/T		
	EFECTOR	Each	
RQANS2	PHOTOELECTRIC 20-250VAC/DC 350MA		
Never Used with used or installed	out all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	aged cosmetically, ite	em has never been



	11/13/2018
Vendor ID:	867499
/endor Name:	JOSEPH KODOS
Rid ID:	433421

			Page 10 of 12
Qty	Part Number Manufacturer Description	U of M	
Item Condition	and Item Notes		
1	135-909-24F3		
	EUPEC	Each	
RQANS2	RECTIFIER 1CONNECTOR		
Never Used with used or installed	nout all original factory packaging some OEM supplied accessory items may be missing. Item is not dama I and is working.	aged cosmetically, ite	em has never been
Part Number 13	5-909-24f3 seemed to be incomplete. The above part number is a possible match. Vendor's part number	er is 135-909-24f3	
2	QPJ-1D100-S2P		
	FANUC	Each	
RQAUS1	Discontinued by manufacturer, 4.7" Q-PANEL JR. QuickPanel Jr. ,STN Color Display ,24 VDC ,Type 4X/12 IP65		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be miss	sing.
Part Number QF	PJ1D100S2P seemed to be incomplete. The above part number is a possible match. Vendor's part num	ber is QPJ1D100S2F	
1	50-162141LSPZ2AAA		
	GENERAL ELECTRIC	Each	
RQANS2	PANEL METER, CURRENT TRASFORMER, 3-1/2 IN, PERCENT MOTOR LOAD CURRENT: 0-150		
Never Used with used or installed	nout all original factory packaging some OEM supplied accessory items may be missing. Item is not dama I and is working.	aged cosmetically, ite	em has never been
Vendor's part nu	ımber is 50-162141LSPZ2AAA		
1	C7027A-1072		
	HONEYWELL	Each	
RQAUS1	MINI PEEPER UVDETECTR -40/250F		
Used in working	$condition, item \ is \ in \ resalable \ condition, \ without \ severe \ cosmetic \ damage, \ some \ OEM \ supplied \ accessors$	ry items may be miss	sing.
Part Number C7	027A1072 seemed to be incomplete. The above part number is a possible match. Vendor's part number	er is C7027A1072	
9	PIL-1		
	KELE & ASSOCIATES	Each	
RQAUS1	Pulse Initiator, LED indicators, Pulse out (unlatch/latch), Command in maintain (off/on), AC or DC operation, Selectable power-up ON or OFF pulse, Snap-track mounted		
Used in working	condition, item is in resalable condition, without severe cosmetic damage, some OEM supplied accesso	ry items may be miss	sing.
Part Number PIL	_ 1 seemed to be incomplete. The above part number is a possible match. Vendor's part number is PIL	1	
10	SA200-2		
	KELE & ASSOCIATES	Each	
RQANS2	CURRENT TRANSDUCER SPLIT CORE 0-200AMP 4-20MA OP		
Never Used with used or installed	nout all original factory packaging some OEM supplied accessory items may be missing. Item is not dama I and is working.	aged cosmetically, ite	em has never been
Lines 70 and 74	were combined. Vendor's part number is SA200-2		
2	7242AD2D5FRX		
	MARSH BELLOFRAM	Each	
RQANS2	PHOTOELECTRIC DIFFUSE BEAMSWITCH TIMER SENSOR		
used or installed		aged cosmetically, ite	em has never been
Vendor's part nu	ımber is 7242AD2D5FRX		
1	7253-AR2-X3A-SX		



Offer to Purchase

	11/13/2018
Vendor ID:	867499
/endor Name:	JOSEPH KODOS
Bid ID:	433421

Part Number Qty Manufacturer U of M		
Description		
Item Condition and Item Notes		
MARSH BELLOFRAM Each		
RQANS2 PHOTOELECTRIC RETO-REFLECTIVE		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never used or installed and is working.	been	
Part Number 7253AR2X3ASX seemed to be incomplete. The above part number is a possible match. Vendor's part number is 7253AR2X3ASX		
1 NL-104X125DA015		
NATIONAL ELECTRONICS Each		
RQANS2 SILICON CONTROLLED RECTIFIER		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never used or installed and is working.	been	
Vendor's part number is NL-104X125DA015		
4 OAC-15		
OPTO 22 Each ROANS2 I/O MODULE; CURRENT RATING:3A; ACCESSORY TYPE:AC OUTPUT MODULE; CONTACT		
RQANS2 I/O MODULE; CURRENT RATING:3A; ACCESSORY TYPE:AC OUTPUT MODULE; CONTACT CONFIGURATION:SPST-NO; COUNT INPUT FREQUENCY:65HZ; EXTERNAL DEPTH:15.2MM; EXTE		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never used or installed and is working.	been	
Part Number OAC15 seemed to be incomplete. The above part number is a possible match. Vendor's part number is OAC15		
23 ODC-5		
OPTO 22		
RQANS2 OUTPUT MODULE, 5-60VDC, 5VDC LOGIC SNAP/PAC		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never used or installed and is working.	been	
Part Number ODC5 seemed to be incomplete. The above part number is a possible match. Vendor's part number is ODC5		
2 CUB2L000		
RED LION CONTROLS Each		
RQANS2 COUNTER, MINIATURE, W/LITHIUM BATTERY, 6DIGIT LCD		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never used or installed and is working.	been	
Vendor's part number is CUB2L000		
5 CUB2L000		
RED LION CONTROLS Each		
RQANS1 COUNTER, MINIATURE, W/LITHIUM BATTERY, 6DIGIT LCD		
Never Used with all original factory packaging, sealed or unsealed, instructions and accessories if normally supplied when purchased from OEM must be present. Item never used or installed, packaging and item match and are undamaged, serial numbers must match.		
Vendor's part number is CUB2L000		
9 98412		
TPC WIRE & CABLE Each		
RQANS2 TAPE INSULATED 1INX36FT Never Used without all original factory packaging some OFM supplied accessory items may be missing. Item is not damaged cosmetically, item has never.	hoon	

used or installed and is working.

Vendor's part number is 98412



Offer to Purchase

Offer Date:	11/13/2018
Vendor ID:	867499
Vendor Name:	JOSEPH KODOS
Bid ID:	433421

Page 12 of 12

Qty	Part Number Manufacturer Description	U of M	
Item Condition a	and Item Notes		
3	ODC-5		
	TYCO	Each	
RQANS2	SOLID STATE RELAY, 3A, 3-8VDC INPUT, 60VDC OUTPUT		
Never Used withoused or installed	but all original factory packaging some OEM supplied accessory items may be missing. Item is not dama and is working.	ged cosmetically, ite	m has never been
Part Number OD	C5 seemed to be incomplete. The above part number is a possible match. Vendor's part number is OD	C5	
1	988L10BDAARR		
	WATLOW	Each	
RQANS2	TEMPERATURE, LIMIT OR PROCESS CONTROLLERS - SERIES 988LF/989LF - AUTO-TUNING CONTROLLERS		
Never Used without all original factory packaging some OEM supplied accessory items may be missing. Item is not damaged cosmetically, item has never been used or installed and is working.			
Part Number 988	L-10BD-AARR seemed to be incomplete. The above part number is a possible match. Vendor's part number is a possible match.	umber is 988L-10BD-	AARR
284	: Total Items If accepted offer will be paid in US Dollars (\$).	Total:	\$ 3,773.30
This offer is ma	de for equipment matching the descriptive information supplied by your company, prior to this o	ffor If this offer is	

This offer is made for equipment matching the descriptive information supplied by your company, prior to this offer. If this offer is accepted Radwell reserves the right to reject and return for full credit any item that is not in the condition stated on this offer. See; "Item Condition and Item Notes". Radwell also reserves the right to return for full credit items that are not the same as the items listed on this offer, such as a different manufacturer or part number then those included on this offer.

	/_/
Bid Accepted, (Your Signature)	Date