5b/6b code

		DD 4	DD 4
Input	T	RD = -1	RD = +1
	EDCBA	abcdei	
D.00	00000	100111	011000
D.01	00001	011101	100010
D.02	00010	101101	010010
D.03	00011	110001	
D.04	00100	110101	001010
D.05	00101	101001	
D.06	00110	011001	
D.07	00111	111000	000111
D.08	01000	111001	000110
D.09	01001	100101	
D.10	01010	010101	
D.11	01011	110100	
D.12	01100	001101	
D.13	01101	101100	
D.14	01110	011100	
D.15	01111	010111	101000

input		RD = -1	RD = +1
	EDCBA	abcdei	
D.16	10000	011011	100100
D.17	10001	100011	
D.18	10010	010011	
D.19	10011	110010	
D.20	10100	001011	
D.21	10101	101010	
D.22	10110	011010	
D.23	10111	111010	000101
D.24	11000	110011	001100
D.25	11001	100110	
D.26	11010	010110	
D.27	11011	110110	001001
D.28	11100	001110	
D.29	11101	101110	010001
D.30	11110	011110	100001
D.31	11111	101011	010100
K.28	11100	001111	110000

RD = +1

3b/4b code

input		RD = -1	RD = +1	input		RD = -1
	HGF	fghj			HGF	fghj
D.x.0	000	1011	0100	K.x.0	000	1011
D.x.1	001	1001		K.x.1	001	0110
D.x.2	010	0101		K.x.2	001	1010
D.x.3	011	1100	0011	K.x.3	011	1100
D.x.4	100	1101	0010	K.x.4	100	1101
D.x.5	101	1010		K.x.5	001	0101
D.x.6	110	0110		K.x.6	001	1001
D.x.P7	111	1110	0001			
D.x.A7	111	0111	1000	K.x.7	111	0111

Control symbols

Control by moots				
input		RD = -1	RD = +1	
	HGF EDCBA	abcdei fghj	abcdei fghj	
K.28.0	000 11100	001111 0100	110000 1011	
K.28.1	001 11100	001111 1001	110000 0110	
K.28.2	010 11100	001111 0101	110000 1010	
K.28.3	011 11100	001111 0011	110000 1100	
K.28.4	100 11100	001111 0010	110000 1101	
K.28.5	101 11100	001111 1010	110000 0101	
K.28.6	110 11100	001111 0110	110000 1001	
K.28.7	111 11100	001111 1000	110000 0111	
K.23.7	111 10111	111010 1000	000101 0111	
K.27.7	111 11011	110110 1000	001001 0111	
K.29.7	111 11101	101110 1000	010001 0111	
K.30.7	111 11110	011110 1000	100001 0111	