CUBAO MOTORS REPAIR

Collision repair and repainting - TIN 277-409-860-000 VAT

REPAIR ESTIMATE

Estimate No.	**EST-26-1630**
Date	**07 October 2026**
Customer	**Rodel P. Santos**
Vehicle / Plate	**2019 Toyota Hilux 2.4 G / NBH 6620**
Insurer / Policy	**Workforce Solutions, Policy WFS-MC-2026-002874**

Description	Amount (PHP)
Front bumper (replace)	15,600.00
Left headlamp assembly (replace)	19,800.00
Labor	9,600.00
Paint and materials	7,000.00

VATable sales	**46,428.57**
VAT 12%	**5,571.43**
TOTAL ESTIMATE (VAT inclusive)	**52,000.00**