BONIFACIO AUTO WORKS

Collision repair and repainting - TIN 214-889-307-000 VAT

REPAIR ESTIMATE

Estimate No.	**EST-26-1245**
Date	**14 October 2026**
Customer	**Teresita G. Cruz**
Vehicle / Plate	**2021 Toyota Innova 2.8 E / NDE 9051**
Insurer / Policy	**Workforce Solutions, Policy WFS-MC-2026-003340**

Description	Amount (PHP)
Front bumper cover (replace)	14,800.00
Hood panel (replace)	18,900.00
Radiator and condenser (replace)	21,500.00
Headlamp assemblies (replace)	19,400.00
Labor	12,000.00
Paint and materials	9,900.00

VATable sales	**86,160.71**
VAT 12%	**10,339.29**
TOTAL ESTIMATE (VAT inclusive)	**96,500.00**