GREENHILLS COLLISION CENTER

Collision repair and repainting - TIN 305-118-442-000 VAT

REPAIR ESTIMATE

Estimate No.	**EST-26-2204**
Date	**15 October 2026**
Customer	**Dennis C. Uy**
Vehicle / Plate	**2023 Honda City 1.5 V / DAK 7316**
Insurer / Policy	**Workforce Solutions, Policy WFS-MC-2026-002281**

Description	Amount (PHP)
Rear bumper cover (replace)	18,200.00
Trunk lid (repair and repaint)	15,600.00
Rear lamp assembly LH (replace)	9,800.00
Labor	16,000.00
Paint and materials	11,700.00

VATable sales	**63,660.71**
VAT 12%	**7,639.29**
TOTAL ESTIMATE (VAT inclusive)	**71,300.00**