BONIFACIO AUTO WORKS

Collision repair and repainting - 118 Aurora Blvd., Quezon City - TIN 214-889-307-000 VAT

REPAIR ESTIMATE

Estimate No.	**EST-26-1187**
Date	**05 October 2026**
Customer	**Ramon A. Dela Cruz**
Vehicle / Plate	**2024 Toyota Vios 1.3 XLE / NCX 4821**
Insurer / Policy	**Policy WFS-MC-2026-004417**

Description	Amount (PHP)
Front bumper cover (replace)	14,500.00
Right headlamp assembly (replace)	21,800.00
Hood panel - repair and repaint	9,600.00
Radiator support - straighten	6,200.00
Front bumper reinforcement	5,300.00
Labor	18,000.00
Paint and materials	11,000.00

VATable sales	**77,142.86**
VAT 12%	**9,257.14**
TOTAL ESTIMATE (VAT inclusive)	**86,400.00**