
Moore state machine state transition diagram

input: n\_rst\_i output: o



Mealy state machine state transition diagram input: n\_rst i

output: o

