TA 985M (Databank) Change-out with ВД-СУ Mode Disabled

| GMT | CREW | ACTIVITY |
|-------------|-------------------|--|
| 06:00-06:10 | | Morning inspection |
| 06:10-06:40 | | Post-sleep |
| 06:40-07:30 | • | BREAKFAST |
| 07:30-07:50 | FE-1 CDR, FE-2 | Work prep |
| 07:30-07:55 | | |
| 07:50-07:55 | FE-1 | PLANTS-2. Equipment monitoring |
| 07:55-08:10 | | Daily planning conference (S-band) |
| 08:10-08:15 | CDR | EXPRESS Rack 2: power on |
| 08:10-09:00 | FE-2 | TOCA setup (Total Carbon Analyzer) |
| 08:10-08:15 | FE-1 | PLASMA CRYSTAL-3. Turbo-pump activation |
| 08:15-08:45 | CDR | GASMAP HRF: power up for 90 day checkout |
| 08:15-09:15 | FE-1 | PLASMA CRYSTAL-3. S/W Installation. Tagup with specialists. (S-band) |
| 08:50-09:00 | CDR | Video setup for imaging physical exercise on TVIS |
| 09:00-09:50 | CDR, FE-2 | SSRMS (DOUG) S/W Review |
| 09:30-09:40 | FE-1 | On MCC Go ISS pressurization with O2 from Progress CpΠK |
| 09:40-10:00 | FE-1 | Test closure of emergency vacuum valves (АВК ВОЗДУХ) |
| 09:50-10:05 | CDR | RED scheduled inspection |
| 09:50-10:25 | FE-2 | TOCA water sample testing |
| 10:00-11:00 | FE-1 | SM: dust filters (ΠΦ)1-4 changeout (the ones with vertical ribs) |
| 10:05-11:35 | CDR | Physical exercise (RED) |
| 10:30-11:10 | FE-2 | СОЖ maintenance |
| 11:00-12:30 | FE-1 | Physical exercise (TVIS, day 2) |
| 11:15-11:35 | FE-2 | TOCA water sample testing |
| 11:55-12:30 | FE-Z | |
| 11:35-12:05 | - CDR | SSRMS Operator Workstation S/W checkout |
| 12:05-12:15 | | Transfer a FOOT file from EMU to Laptop |
| 12:15-12:25 | | Setup/prep for PAO event |
| 12:25-12:35 | | Prep for PAO event |
| 12:30-13:30 | FE-1, FE-2 | LUNCH |
| 12:35-12:50 | CDR | TV downlink (PAO) (Ku+S-band) |
| 12:50-13:50 | | LUNCH |
| 13:30-14:35 | FE-1 | SM ventilation system preventative maintenance. Group A |
| 13:30-13:40 | - FE-2 | InSPACE: video setup |
| 13:40-14:25 | | InSPACE: observation |
| 13:50-14:50 | CDR | GASMAP HRF: 90 day checkout |
| 14:25-14:40 | FE-2 FE-1 | Private medical conference (Ku+S-band) |
| 14:40-14:55 | | |
| 14:45-14:55 | FE-2 | CDM battery install |
| 14:50-15:10 | CDR | GASMAP HRF: 90 day checkout |
| 14:55-16:55 | FE-1 | БИТС-2-12: TA 985M (Data bank) change-out. Tagup with ground |

| | | anacialista (VHE(VVP) S hand) |
|----------------|------------|---|
| | | specialists(VHF(УКВ), S-band) |
| 14:55-15:55 FE | E-2 | Physical exercise (TVIS) |
| 15:10-15:20 | CDR | GASMAP HRF: checkout |
| 15:20-16:20 | | FOOT: Setup |
| 15:55-16:00 | FE-2 | Weekly TVIS maintenance |
| 16:00-16:10 FE | | CDM battery stow |
| 16:10-17:40 | | Physical exercise (RED) |
| 16:20-16:50 | CDR | FOOT: equipment calibration prep for CDR electromyography |
| 16:50-17:50 | | Physical exercise (TVIS) |
| 16:55-17:55 FE | Ξ-1 | Physical exercise (VELO + Load Trainer 1, day 2) |
| 17:40-18:15 FE | E-2 | Transfer CDM data to MEC |
| 17:50-18:00 CE | OR | Stow video hardware for imaging physical exercise on TVIS |
| 17:55-18:25 FE | E-1 | IMS file prep |
| 18:00-18:15 CE | OR | Private medical conference (Ku+S-band) |
| 18:15-18:45 CE | DR, FE-2 | Daily plan review |
| 18:25-18:45 FE | E-1 | Daily plain review |
| 18:45-19:00 | | Daily planning conference (S-band) |
| 19:00-19:30 | | Evening work prep |
| 19:30-20:00 | | DINNER |
| 20:00-20:30 | | Daily food prep |
| 20:30-21:25 FE | E-1 | Pre-sleep |
| 20:30-21:30 CE | OR, FE-2 | |
| 21:25-21:30 FE | E-1 | PLASMA CRYSTAL-3. Turbo-pump deactivation |
| 21:30-06:00 | | SLEEP |

Note: See OSTP for references to missing US activities.

End of Radiogram