radiogram 8471u Form 24 for 07.26.04

Transition from [PCO] to [OCK] Attitude. Purging and Evacuation of Fuel [ЗУГ] and Oxidizer [ЗУО] Loading Devices

Loading Devices			
GMT	Crew	Activity	
06:00-06:10		Morning inspection	
06:10-06:20	CDR	Post-sleep	
	FE-1	Calf volume measurement	
06:20-06:30	CDR	- Volume measurement	
	FE-1	MO-8. System config	
06:30-06:45	CDR	Post-sleep	
	FE-1	Body mass measurement	
06:45-07:00	CDR		
06:45-07:10	FE-1	Post-sleep	
07:00-07:10	CDR	MO-8. Close-out ops	
07:10-07:50		BREAKFAST	
07:50-08:05		DPC (S-band)	
08:05-08:20		BREAKFAST	
08:20-08:45		Work prep	
08:45-09:00	CDR	Regeneration of БМП cartridge Φ1 (end)	
08:45-08:50	FE-1	Payload status check in LAB	
08:50-09:00		FMK deployment ops	
09:00-10:15		Unstow equipment and tools for EVA-10. Tagup with specialists (S-band)	
10:15-11:45	FE-1	Physical exercise (RED)	
10:15-10:55	CDR	Photography of videometer target and Laser Retro-reflector [УК ЛСВ-М] in preparation for EVA-10	
11:00-12:00		Physical exercise (TVIS) day 4	
11:45-12:00	FE-1	Questionnaire: journal entry	
12:00-12:30		СОЖ maintenance (Inspection of БРПК)	
12.00-12.50	CDR	Physical exercise (RED)	
12:30-13:30		LUNCH	
13:30-16:25		Unstow equipment and tools for EVA-10. Tagup with specialists. (S-band)	
16:25-16:55	FE-1	EVA support panel [ΠΟΒ] check in ΠxO	
		EVA support panel [ΠΟΒ] check in ΠxO	
16:55-17:10	CDR	TV imagery and downlink of equipment prep (Ku+S-band) and Tagup with specialists (S-band)	
16:55-17:55	FE-1	Physical exercise (TVIS)	
17:10-18:10	CDR	Physical exercise (VELO + Force Loader/ cycle-1) day 4	
17:55-18:00	FE-1	Weekly TVIS maintenance	
18:00-18:20		IMS file prep	
18:15-18:45	CDR FE-1	Daily plan ravious	
18:20-18:50		Daily plan review	
18:50-19:05		DPC (S-band)	
19:05-19:35	FE-1	Report prep	
19:05-19:30	CDR		

19:30-20:00		Daily food prep
19:35-20:00	FE-1	
20:00-20:30		DINNER
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	CDR	URAGAN

Note: See OSTP for references to USOS activities

End of radiogram