Preventive maintenance of ventilation system. PLASMA CRYSTAL

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection of the station
06:10-06:20	CDR	MO-8. Set up.
	FE-1	Calf volume measurement
06:20-06:30	CDR	
06:20-06:35	FE-1	Body mass measurement
06:35-06:50	CDR	
06:35-06:55	FE-1	Post-sleep
06:50-07:00	CDR	MO-8. Closeouts
06:55-07:30	FE-1	BREAKFAST
07:00-07:30	CDR	Post-sleep
07:30-08:00	FE-1	Prep for work
07:30-07:55	CDR	Trep for work
07:55-08:00	CDIX	PLANTS-2. Hardware operation monitoring
08:00-08:15		Daily planning conference (S-band)
08:15-08:20	FE-1	GLOVEBOX (MSG) - Activation
08:15-09:00	CDR	BREAKFAST
08:20-08:35	FE-1	Coarsening in Solid Liquid Mixtures (CSLM2) – initial ops 1
08:40-09:40		Preventive maintenance of SM ventilation system, group A
09:00-10:30	CDR	PLASMA CRYSTAL. Hardware setup. Tagup (S-band)
09:40-11:00	FE-1	Changeout of dust filter cartridges ΠΦ1, ΠΦ2 and fans B1, B2 grille cleaning in DC1
10:30-10:50	CDR	PLASMA CRYSTAL -3. Seal check before vacuum. Tagup (S-band)
10:50-11:30		BB2PO airduct fan grille cleaning
11:10-12:25	FE-1	Physical exercise (TVIS)
11:30-12:30	CDR	PLASMA CRYSTAL. 35 work chamber vacuuming. Tagup (S-band)
12:25-12:30	FE-1	Weekly maintenance of TVIS
12:30-13:30		LUNCH
13:30-13:40	FE-1	PAO set up
13:40-13:50		PAO event prep
13:50-14:10		PAO. ISS:1000 days in space
14:10-14:50	CDR	Maintenance of СОЖ
14:30-15:30	FE-1	SSC6: Troubleshooting of communication port 1
14:50-15:30	CDR	ISS file prep
15:30-18:00		PROFILAKTIKA. Cycloergometer experiment. Tagup (S-band)
15:30-16:30	FE-1	Prep for Payload educational event
16:35-17:50		Physical exercise (RED)
17:55-18:00		GLOVEBOX (MSG) – Power off
18:00-18:10		Weekly payload status check – Expedition 7

	Daily plan review
	Daily planning conference (S-band)
	Prep for work
	Daily food prep
	DINNER
FE-1	Pre-sleep
CDR	— I те-эісер
	PLASMA CRYSTAL: Deactivation of turbo pump.
	SLEEP

Note: See OSTP for references to US activities.

End of radiogram