Radiogram 6494u Form 24 for 09.15.03

## Satellite Navigation System (ACH-2) Deactivation • ИДЭ-2 Smoke Detectors Changeout in DC-1.

GMT	Crew	Activity
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Prep for work
08:00-08:15		Daily planning conference (S-band)
08:15-08:45		СССП kit familiarization (GPS unit and Motorola telephone). <i>Tag up with specialists (S-band)</i>
08:45-10:15	FE-1	EPO: procedure review
08:45-10:45	CDR	Smoke detector ИДЭ-2 changeout in DC-1
10:15-10:20	FE-1	UOP cable connection to display and control panel
10:20-10:30		Daily payload status check
10:30-10:35		Comparison of CSA analyzers
10:35-11:50		Physical exercise (TVIS)
10:45-10:50	000	БРПК-2 separator inspection
10:50-11:50	CDR	Physical exercise (Velo + Load Trainer-1/Day 3)
11:50-12:50		LUNCH
12:50-16:20	FE-1	RED repair
12:50-13:10	CDR	IMS file prep
13:50-15:50		RED repair
16:15-16:25		TVIS twice-a-month inspection
16:20-16:50	FE-1	HPA: onboard training

16:25-17:55	CDR	Physical exercise (TVIS-3)
16:50-16:55	FE-1	Ham radio equipment setup
16:55-17:05		Ham radio pass
17:10-18:25		Physical exercise (RED)
17:55-18:25	CDR	СОЖ maintenance
18:25-18:40		Daily planning conference (S-band)
18:40-19:00		Daily plan review
19:00-19:30		Prep for work
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP

Note: See OSTP for references to US activities

End of radiogram