Form 24 for 02.13.03

Robotics Ops

GMT	Crew	Activity
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:00	CDR	Acoustic dosimeters: stowage
06:40-07:30	FE-1, FE-2	BREAKFAST
07:00-07:40	CDR	BINEARI AGT
07:30–07:40	FE-2	Prep for work
	FE-1	PLANTS-2: payload powerdown
07:40-07:55		Daily planning conference (S-band)
07:55–08:15	FE-1, FE-2	Prep for work
07:55–08:30	CDR	r rep for work
08:15–08:30	FE-1	SAMS filter cleanup
08:15–08:20	FE-2	ACS CDMK CO2 read
08:30-08:40	FE-1	SAMS ICM deactivation (section 1)
08:30-08:45	CDR	LAB CCAA reconfig
08:45-09:30	CDIX	FOOT data transfer
09:00-09:30	FE-1	PLASMA CRYSTAL-3: video downlink
09:10–10:40	FE-2	Physical exercise (RED)
09:30–11:00	FE-1	SM battery 800A (№7) R&R
09:50–10:00	CDR	FOOT: prep for data downlink
10:00–11:00	ODIC	Physical exercise (TVIS)
10:40–11:40	FE-2	Physical exercise (CEVIS)
11:00–12:30	FE-1	Physical exercise (TVIS-4)
11.00-12.00	CDR	Physical exercise (RED)
11:40–12:20	FE-2	Maintenance of СОЖ
12:30–12:35	FE-1	Laptop 3 battery cycle (start)
12:30–13:30	CDR, FE-2	LUNCH
12:35–13:30	FE-1	LUNCH
13:30–13:50	F C - 1	IMS tagup (S-band)
13:30–17:30	CDR, FE-2	Robotics ops
13:50–14:50	FE-1	Photography of the scratch left by the Progress docking probe on the ПрК cone
13:50–15:30		Scratch left by the Progress docking probe: transfer of digital imagery to the computer
15:50–16:30		IMS file prep
16:30–17:30		Physical exercise (VELO + Load Trainer-1 / day 4)
17:30–18:05		Prep for work
17:30–18:05	CDR	FOOT data downlink (end)
17:30–17:35	FE-2	ACS CDMK CO2 read
18:05–18:20		Private conference w/ friends (KU+S-band)

18:20–18:45		Daily plan review
18:45–19:00		Daily planning conference (S-band)
19:00–19:20	FE-1	Laptop 3 battery cycle (en)
19:00–19:30	CDR, FE-2	Prep for work
19:30–20:00		DINNER
20:00–20:30		Daily food prep
20:30–21:30		Pre-sleep
21:30–06:00		SLEEP

NOTE: See OSTP for references to US procedures

End of radiogram