Radiogram No. 6820u Form 24 for 01/02/08 **Progress Unloading. PROFILAKTIKA Experiment.** 

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30	1.	BREAKFAST
07:30-07:50	CDR	Prep for Work
07:30-08:00	FE-1,FE-2	Prep for Work
07:50-08:00	CDR	CSLM2 - Open Vacuum Vent 4
08:00-08:15		Daily Planning Conference (S-band)
08:15-09:15	CDR	PMA3 repress
08:15-08:55	FE-1	Cleaning ВД1 and ВД2 air ducts in DC-1
08:30-10:00	FE-2	Physical Exercise (RED)
09:00-09:15	FE-1	URAGAN. Observations and photography
09:15-09:45	CDR	PCBA Blood Test - hardware setup
09:15-11:45	FE-1	PROFILAKTIKA. Cycle Ergometer Experiment. Tagup with specialists (S-band)
09:45-10:15	CDR	PMA3 leak check
10:10-10:15	FE-2	Opening Node 1 Nadir Hatch
10:15-10:35	FE-2	Removal of CBM Center Disk Cover
10:15-11:45	CDR	Physical Exercise (RED)
10:35-11:35	FE-2	CBM CPA Dismantling
11:35-12:35	FE-2	Physical Exercise (TVIS)
11:45-12:00	FE-1	Taking readings from AOK ГАНК-4M Gas Analyzer
11:45-12:15	CDR	Centerline Berthing Camera System (CBCS) Pressurized Mating Adaptor (PMA) Target Assembly Removal
12:15-12:35	CDR	Transfer of BMRRM from PMA3
12:30-13:00	FE-1	Counter Measure System (CMS) Harmful Contaminant Measurements in SM. Tagup with specialists (as necessary) (S-band)
12:35-13:05	CDR	InSPACE2 – familiarization
12:35-13:05	FE-2	Hatch Handle Guide Ring (HHGR) Installation in Node1
13:00-13:05	FE-1	On MCC Go ISS O2 repress from Progress 362 CpΠK (start)
13:05-14:05		LUNCH
14:05-14:10	FE-1	ISS O2 repress from Progress 362 CpΠK (terminate)
14:05-14:20	FE-2	Start Filling CWC from the Lab Condensate Tank
14:05-14:35	CDR	Centerline Berthing Camera System (CBCS) Pressurized Mating Adaptor (PMA) Target Assembly Installation
14:10-16:05	FE-1	Progress 362 Unloading and IMS Updates
14:35-15:35	CDR,FE-2	UDM Controller Panel Assembly Installation
15:35-15:50	FE-2	Terminate filling CWC from Lab Condensate Tank
15:55-16:10	FE-2	USOS hatch seal inspection
16:05-16:25	FE-1	Cleaning БВН [Heater Fan ] Screen in Soyuz
16:05-16:25	CDR	Installation of CBM Center Disk Cover
16:20-16:25	FE-2	BCAT-3: camera checkout
16:25-17:35	CDR	Progress 362 Unloading and IMS Updates

16:25-16:55	FE-2	Crewlock Stowage Removal In Preparation for PMA3 Depress Pump Operations
16:25-16:40	FE-1	IRIDIUM phone charging setup, start charge Tagup with specialists as necessary (S-band)
16:40-16:50	FE-1	Maintenance Closures of Vozdukh ABK Valves
16:50-16:55	FE-1	IRIDIUM phone charging - status check
16:55-17:10	FE-1	Private Medical Conference (Ku + S-band)
16:55-18:25	FE-2	PMA3 Depress
17:10-17:15	FE-1	IRIDIUM phone charging - status check
17:15-17:30	FE-1	Verify ИП-1 Sensor Positions
17:30-17:35	FE-1	IRIDIUM phone charging - status check
17:35-17:45	FE-1	IRIDIUM phone charging - terminate charge, cleanup
17:35-18:35	CDR	Physical Exercise (TVIS)
17:45-18:05	FE-1	IMS update
18:05-18:35	FE-1	Evening work prep
18:35-19:15	FE-1	СОЖ Maintenance
18:35-18:40	CDR	LAN MSG cable reconfig in Express rack 5
18:40-18:45	FE-2	Transfer TVIS/RED/CEVIS/HRM data to MEC
18:40-18:55	CDR	Private Medical Conference (Ku+S-band)
18:45-18:50	FE-2	Disconnect LTL jumper from LAB1D6 rack after CDRA Deactivation
18:50-19:15	FE-2	Evening work prep
18:55-19:15	CDR	Evening work prep
19:15-19:30		Daily Planning Conference (S-band)
19:30-20:00	CDR,FE-1	Daily food prep
19:30-19:45	FE-2	Daily food prep
19:30-19:45	FE-2	Pre-sleep
19:45-20:00	FE-2	VHF comm. test using US ground sites
20:00-20:30		DINNER
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP

Note: 1. See OSTP for references to US activities.

2. SM Window #9 shutter opening is at crew discretion End of Radiogram