Form 24 for 08/01/02

Single-Burn ISS Reboost Using Progress Thrusters Commanded Via YC-21

GMT	Crew	Activity
06:00-06:10		Morning inspection
06:10-06:15	FE-2	PLASMA CRYSTAL-3: turbo-pump activation
06:10-06:40	CDR, FE-1 FE-2	Post-sleep
06:15–06:40		
06:40-07:30		BREAKFAST
07:30-08:00	CDR, FE-2	Work prop
07:30-07:55	FE-1	Work prep
07:55–08:00	F E - I	DCP bypass cable reconfig (ROBOTICS)
08:00-08:15		Daily planning conference (S-band)
08:15-08:45	FE-1	SUBSA: test activation
08:15-08:35	CDR	On MCC GO: ISS repress with O2 from Progress CPПK system
08:15-08:45	FE-2	Urine transfer to Progress RODNIK tank (config)
08:45-09:45	F E - Z	Urine transfer to Progress RODNIK tank
08:35-08:40	CDR	Inspection of БРПК-2 separator
09:00–10:30	CDR	Physical exercise (VELO+Load Trainer)
09:20-10:50	FE-1	Physical exercise (RED)
09:45–10:00	FE-2	Tagup with ground specialists (onboard computers and SIGMA trajectory forecast software) (S-band)
10:30–12:00	FE-2	Physical exercise (VELO+Load Trainer)
10:30–11:10	CDR	Maintenance of СОЖ
10:50–11:50	FE-1	Physical exercise (TVIS)
11:10–11:50	CDR	IMS file prep
11:50–12:10	FE-1	SUBSA: specimen placement
12:00–12:40	FE-2	PLASMA CRYSTAL-3: experiment prep. Tagup w/ ground specialist (S-band)
12:00–12:20	CDR	Setup for PHS
12:10-12:30	FE-1	SUBSA: payload ops (steps 1-6) 2 nd run
12:20–13:20	CDR	LUNCH
12:30–13:20	FE-1	
12:40–13:15	FE-2	PLASMA CRYSTAL-3: experiment ops. TELESCIENCE video link. Tagup w/ ground specialist (S-band)
13:15–14:15		LUNCH
13:30–17:30	CDR, FE-1	SSRMS ops
14:15–14:35	FE-2	PLASMA CRYSTAL-3: experiment ops (end)
14:35–14:55		Urine transfer to Progress RODNIK tank
14:55–15:25		PLASMA CRYSTAL-3: experiment ops (data copying and payload deactivation). Tagup w/ ground specialist (S-band)
15:25–15:45		Uring transfor to Progress PODNIK tank
16:05–16:25		Urine transfer to Progress RODNIK tank
16:25–17:25		Physical exercise (VELO-1)

17:25–17:45		Urine transfer to Progress RODNIK tank
17:30–17:40	FE-1	SUBSA: payload ops (step 7) 2 nd run
17:30–18:30	CDR	Physical exercise (VELO-1)
17:40–17:50	FE-1	Payload status check
17:45–18:00	FE-2 FE-1	UROLUX equipment setup
18:00–18:25		Daily plan review
18:15–18:45		
18:25–18:45	FE-2	Urine transfer to Progress RODNIK tank
18:30–18:45	CDR	Daily plan review
18:45–19:00		Daily planning conference (S-band)
19:00–19:10	FE-2 CDR, FE-1	Work prep
19:00–19:30		
19:10–19:50	FE-2	Urine transfer to Progress RODNIK tank
19:50–20:20		Urine transfer to Progress RODNIK tank (teardown)
19:30–20:00	CDR, FE-1	DINNER
20:00–20:30		Daily food prep
20:20–20:50	FE-2	DINNER
20:30–21:30	CDR, FE-1	Pre-sleep
20:50–21:25	FE-2	те эксер
21:25–21:30		PLASMA CRYSTAL-3: turbo-pump deactivation
21:30–06:00		SLEEP

Note: See OSTP for references to US activities. End of radiogram