Pressurizing Section 1 of Progress КДУ Manifold

-		f Progress КДУ Manifold
GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40	FE-1	Post-sleep
06:10-06:50	CDR	
06:40-06:50	FE-1	Calf measurement
06:50-07:40	FE-1	BREAKFAST
06:50-07:00	CDR	Calf measurement
07:00-07:40	CDR	BREAKFAST
07:45-08:15		Work prep
08:15-08:30		Daily planning conference (S-band)
08:30-08:50	FE-1	Inspection of internal portion of PCMCIA top opening on HRF computer <i>Tagup</i> with specialists (S-band)
08:30-11:00	CDR	Shuttle hardware prepack
08:50-11:05	FE-1	- Shuttle Hardware prepack
11:00-12:30	CDR	Physical Exercise (TVIS) Day 4
11:05-11:35	FE-1	Troubleshooting of SSC laptop display
11:35-12:25		Dust collectors ΠΦ1, ΠΦ2 - filter replacement, fans B1, B2 - grille cleaning in DC1 /(ΦΓΕ_307_1, ΦΓΕ_303_1, Report to MCC or update IMS)
12:30-13:30		LUNCH
13:30-14:30	CDR	SM ventilation system preventive maintenance. Group A
13:30-13:35	FE-1	Installation of SLIB interface unit
13:35-14:05		Video recorder bypass cable config set-up
14:05-15:05		CPS hard disk ghost image
15:00-15:30	CDR	СОЖ maintenance
15:05-16:05	FE-1	Physical Exercise (TVIS)
15:30-16:30	CDR	ISS RS plug in audit
16:05-16:10	FF 4	TVIS Weekly Maintenance
16:10-16:40	= FE-1	Physical Exercise (RED)
17:00-17:20	CDR	IMS file prep
17:20-18:20		Physical exercise (VELO + Load Trainer/Cycle 1), day 4
18:00-18:05	FF 4	Transfer TVIS, RED, and HRM data to MEC.
18:05-18:20	FE-1	Questionnaire - FE-1 log entry
18:20-18:35	CDR	Private medical conference (S-band)
18:20-18:40	FE-1 CDR	Daily plan review
18:35-18:55		
18:40-18:55	FE-1	Private medical conference (S-band)
18:55-19:10		Daily planning conference (S-band)
19:10-19:30		Report prep
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
		page to LIC activities

Note: See OSTP for references to US activities.

End of Radiogram