Refuel of FGB Low Pressure Fuel Tanks (БНДГ) 1, 2, 3 and Low Pressure Oxidizer Tanks (БНДО) 1, 2, 3 from Progress КДУ Tank 1

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40	CDR	Post-sleep
06:10-06:50	FE -1	
06:40-06:50	CDR	Calf valuma magaurament
06:50-07:00	FE -1	Calf volume measurement
06:50-07:40	CDR	DDEAKEAST
07:00-07:40	FE -1	BREAKFAST
07:40-07:55		Work prep
07:55-08:10		Daily planning conference (S-band)
08:10-08:25		Work prep
08:25-10:55	CDR	Stow discarded hardware in Progress 352 (with IMS support)
08:25-10:25	FE -1	US hardware setup for stowage in Progress 352
10:25-11:55		Physical exercise (RED)
10:55-11:55	CDR	Physical Exercise (VELO + Force Loader), day 2
11:55-12:30		SFOG candle replacement and activation. Report to MCC numbers of the used candle
11:55-12:55	FE -1	Physical Exercise (TVIS)
12:30-13:00	CDR	СОЖ maintenance
13:00-14:00		LUNCH
14:00-15:30		Stow discarded hardware in Progress 352 (with IMS support)
15:00-15:05		IP Dropbox restart (Dropbox is not accessible)
15:30-17:00	CDR	Physical Exercise (TVIS), Day 2
15:30-16:30	FE -1	US hardware setup for stowage in Progress 352
16:30-17:30		FOOT - hardware assembly
17:00-17:35	CDR	SFOG candle replacement and activation. Report to MCC numbers of the used candle
17:30-18:00	FE -1	FOOT- calibration prep
17:35-17:55	CDR	IMS file prep
18:00-18:15	FE -1	Questionnaire - log entry
18:05-18:20	CDR	URILUX hardware setup
18:15-18:20	FE -1	TVIS, RED, and HRM data transfer to MEC
18:20-18:35		Daily planning conference (S-band)
18:35-19:00		Daily plan review
19:00-19:30		Report prep
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	CDR	PLANTS. Payload status check
I dan Liat		URAGAN Observations and photo imagery

Note: See OSTP for references to US activities.

End of radiogram