Radiogram No. 5449u CREW OFF DUTY

Form 24 for 02/23/2011

GMT	CREW	ACTIVITY
06:00-06:10	FE-1, FE-2	Morning Inspection
	CDR	Reaction Self Test
	FE-4	Elektron-VM Aerosol Filter Inspection
06:00-06:05	FE-6	
	FE-5	Reaction Self Test
06:05-06:10	CDR, FE-4 , FE-5 , FE-6	Morning Inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:50	FE-1, FE-2, FE-4, FE-5, FE-6	Work Prep
07:30-07:45	CDB	Work Prep
07:45-07:55	CDR	Terminate LTL flow through LAB1S6 CCAA
07:55-08:00	CDR, FE-6	BCAT5 - historical documentation photos of crew members
08:00-08:25		Daily Planning Conference (S-band)
08:25-10:40	FE-1	Replacement of MRM1 Terminal Computing Device . Tagup with specialists (S-band)
08:25-09:05	FE-2	Sampling condensate water [KAB] upstream of CPB-K2M Gas-Liquid Mixture Filter [ΦΓC]- Sampler Removal (return on ULF5)
08:25-09:00	FE-6	Actiwatch Initialization
08:30-09:30	FE-4	Physical Exercise (ARED)
08:35-09:35	CDR	DOUG Software Review
08:45-09:00		EPO Greenhouse Hydration And Monitoring
09:00-10:00	FE-5	VSW Relocate
09:00-09:30	EE 0	BIORHYTHM Measurement 1
09:30-10:15	FE-6	Stowage Location Cleanout /NOD1D2 O5
09:30-11:00	FE-4	Physical Exercise (TVIS), Day 2
09:35-10:35	CDR	Physical Exercise T 2
10:00-11:30	FE-5	Physical Exercise (ARED)
10:15-11:45	FE-6	Stowage Location Cleanout /NOD2 O5
10:35-10:45	CDR	Common Cabin Air Assembly (CCAA): Humidity Separator
10:40-11:40	FE-1, FE-2	Orthostatic Stability Evaluation with LBNP. To=11:13 Tagup with specialists (VHF)
10:45-10:55	CDR	IFM: Rack Access
11:00-11:10	FE-4	PAO Hardware Setup
11:10-11:20		Crew Prep For PAO
11:20-11:50		TV PAO for Russia Today TV Channel (Ku + S-band)
11:30-12:30	FE-5	Physical Exercise T2
11:35-11:50	CDR	Cube Lab Data Collection
11:45-13:15	FE-6	Physical Exercise (ARED)
11:50-12:10	FE-4	Sampling condensate water upstream of CPB-K2M 5KO (Water Purification Column Assy) - set up, install bag
11:50-12:00	CDR	N1 Hatch Unlatch
12:00-13:00		Node1 nadir: Centerline Berthing Camera System (CBCS): Checkout
12:10-12:25	FE-4	Verify ИП-1 Flow Meter Configuration
12:15-13:15	FE-1, FE-2	Orthostatic Stability Evaluation with LBNP. To=12:47 Tagup with specialists (VHF)
12:30-12:40	FE-5	T2 Snubber Arm Inspection

13:00-14:00 CDR	12:40-12:45		Set Up Video Equipment to Film ARED Exercise
13.05-13:15 FE-4		CDR	
13:15-14:15		1 -	
14:15-16:15		FE-4, FE-5,	
14:15-15:15 FE-1 Replacement of CД 1-6 Light in Soyuz 701 14:15-14:25 FE-2 KCD2 4F E4 Half-Coupling Shell Coolant Leak Check 14:50-15:30 FE-6 DOUG Software Review 14:50-15:30 FE-4 COX Maintenance 15:30-17:00 FE-6 Private Psychological Conference RVU inspection and photo documentation, as necessary, Part 3 15:45-16:45 FE-2 Physical Exercise (TVIS), Day 1 15:45-16:35 FE-6 VOZmax PPFS Stowage 16:10-16:30 FE-4 CV5A-5CIH Log File Dump 16:20-16:30 CDR CCA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 FE-6 Physical Exercise (TVIS), Day 1 16:50-17:05 FE-6 Physical Exercise (TVIS), Day 1 16:50-17:05 FE-6 Physical Exercise (TVIS), Day 1 16:50-17:05 FE-6 VO2 Stowage 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 FE-6 NA Hardware Deactivation	14:00-16:20	CDR	CCAA: Removal and Changeout of Water Separator
14:15-14:25 FE-2 KOБ2 4 F B 4 Half-Coupling Shell Coolant Leak Check 14:15-15:15 FE-6 DOUG Software Review 14:50-15:30 FE-6 COЖ Maintenance 15:30-15:45 FF-6 Private Psychological Conference 15:30-17:00 FE-1 Physical Exercise (TVIS), Day 1 15:45-16:45 FE-2 Physical Exercise (ARED) 16:10-16:30 FE-4 VO2max PPFS Stowage 16:10-16:30 FE-4 CY5A-BCΠH Log File Dump 16:30-16:40 CDR CCAA: Restow Water Separator 16:40-16:50 CDR, FE-5 (IFM): Rack Restow 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 FE-6 Physical Exercise (TVIS), Day 1 16:50-17:10 FE-4 MS Update 17:05-17:10 FE-4 MS Update 17:05-17:35 FE-6 YO2 Stowage 17:05-17:35 FE-6 PAO Hardware Deactivation 17:05-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:05-17:30 FE-5 Reintliate LTL t	14:15-16:15	FE-5	Hardware Prepack for Return on ULF5
14:15-15:15 FE-6 DOUG Software Review 14:50-15:30 FE-4 COX Maintenance 15:15-15:30 FE-6 Private Psychological Conference 15:30-15:45 FE-6 RVU inspection and photo documentation, as necessary, Part 3 15:30-17:00 FE-1 Physical Exercise (TVIS), Day 1 15:45-16:45 FE-2 Physical Exercise (ARED) 15:45-16:35 FE-6 VO2max PPFS Stowage 16:30-16:30 CDR CCA4: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:10 FE-3 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 FE-6 PAO Hardware Deactivation 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 Reliation Exer	14:15-15:15	FE-1	Replacement of СД 1-6 Light in Soyuz 701
14:50-15:30 FE-4	14:15-14:25	FE-2	КОБ2 4ГБ4 Half-Coupling Shell Coolant Leak Check
15:15-15:30 FE-6 Private Psychological Conference 15:30-15:45 FE-1 Physical Exercise (TVIS), Day 1 15:45-16:45 FE-2 Physical Exercise (TVIS), Day 1 15:45-16:35 FE-6 VOZmax PPFS Stowage 16:10-16:30 FE-4 CV5A-BCΠH Log File Dump 16:20-16:30 CDR CCAA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 CRR, FE-5, FE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 FE-6 VO2 Stowage 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA	14:15-15:15	FE-6	DOUG Software Review
15:30-15:45 FE-6 RVU inspection and photo documentation, as necessary, Part 3 15:30-17:00 FE-1 Physical Exercise (TVIS), Day 1 15:45-16:45 FE-2 Physical Exercise (ARED) 15:45-16:35 FE-6 VO2max PPFS Stowage 16:10-16:30 CDR CCAA: Restow Water Separator 16:20-16:30 CDR CCAA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5 FE-6 Physical Exercise (TVIS), Day 1 16:50-17:05 CDR, FE-5 PAO Event 16:50-17:05 FE-6 VO2 Stowage 17:05-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:10-17:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-6 Physical Exercise T 2 18:10-18:20 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 FE-4 Elektron-VM Aerosol Filter Inspection 19:30-21:30 FE-5 FE-6 Pre-sleep 19:30-21:25 FE-5 FE-6 Pre-sleep 19:30-21:25 FE-5 FE-6 Pre-sleep 19:22-21:30 FE-5 Recition Self Test 19:22-21:30 FE-5 RECITION Test	14:50-15:30	FE-4	СОЖ Maintenance
15:30-17:00 FE-1	15:15-15:30	FE-6	Private Psychological Conference
15:45-16:45 FE-2 Physical Exercise (ARED) 15:45-16:35 FE-6 VO2max PPFS Stowage 16:10-16:30 FE-4 CV5A-5CIH Log File Dump 16:30-16:40 CDR CCAA: Restow Water Separator 16:40-16:50 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 CDR, FE-5, FE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-17:30 FE-6 VO2 Stowage 17:05-17:30 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:20 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektr	15:30-15:45		RVU inspection and photo documentation, as necessary, Part 3
15:45-16:35 FE-6 VO2max PPFS Stowage 16:10-16:30 FE-4 CY5A-5CTIH Log File Dump 16:20-16:30 CDR CCAA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5, EE-6 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 CDR, FE-5, EE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:35 FE-6 VO2 Stowage 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-KZM BKO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 19:30-21:30 FE-1, FE-2, FE-6 Pre-sleep 19:30-21:20 FE-5, FE-6 Pre-sleep	15:30-17:00	FE-1	Physical Exercise (TVIS), Day 1
16:10-16:30 FE-4 CYBA-BCFIH Log File Dump 16:20-16:30 CDR CCAA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CDR, FE-5, FE-6 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 CDR, FE-5, FE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:30 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 19:30-21:30 FE-1, FE-2, FE-6 Pre-sleep 19:30-21:25 FE-5, FE-6 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up	15:45-16:45	FE-2	Physical Exercise (ARED)
16:20-16:30 CDR CCAA: Restow Water Separator 16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 CCR, FE-5, FE-6 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 FE-4 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Fitter Inspection 18:35-19:00 Evening Work Prep 19:30-21:30 FE-5, FE-6 Pre-sleep 19:30-21:25 FE-5, FE-6 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:30	15:45-16:35	FE-6	VO2max PPFS Stowage
16:30-16:40 CDR, FE-5 (IFM): Rack Restow 16:40-16:50 FE-6, FE-6 Crew Prep For PAO 16:45-18:15 FE-2 Physical Exercise (TVIS), Day 1 16:50-17:05 CDR, FE-5, FE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 6KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-6 Reinitiate LTL to the LAB1S6 CCAA 18:35-19:00 FE-1 Elektron-VM Aerosol Filter Inspection 19:30-21:30 FE-4 Elektron-VM Aerosol Filter Inspection 19:30-21:30 FE-1, FE-2, FE-6 Pe-sleep 19:30-21:30 FE-1, FE-2, FE-6 Pre-sleep 21:20-21:25 FE-5, FE-6 FE-6 21:20-21:25 FE-6 FE-6 <t< td=""><td>16:10-16:30</td><td>FE-4</td><td>СУБА-БСПН Log File Dump</td></t<>	16:10-16:30	FE-4	СУБА-БСПН Log File Dump
16:40-16:50 CDR, FE-5, FE-6 FE-6 FE-6 FE-6 FE-6 FE-6 FE-6 FE-6	16:20-16:30	CDR	CCAA: Restow Water Separator
16.45-18.15 FE-6	16:30-16:40	CDR, FE-5	(IFM): Rack Restow
16:50-17:05 CDR, FE-5, FE-6 PAO Event 16:50-17:10 FE-4 IMS Update 17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 FE-1, FE-2, FE-6 Pre-sleep 19:30-21:30 FE-5, FE-6 Pre-sleep 19:30-19:35 FE-5, FE-6 Pre-sleep 19:35-21:20 Pre-sleep 21:20-21:25 FE-5 Reaction Self Test MPC Power Down MPC Power Down	16:40-16:50		Crew Prep For PAO
FE-6	16:45-18:15	FE-2	Physical Exercise (TVIS), Day 1
17:05-17:35 FE-6 VO2 Stowage 17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:30 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test MPC Power Down Reaction Self Test	16:50-17:05		PAO Event
17:05-17:10 FE-5 PAO Hardware Deactivation 17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reintitate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:30 FE-5, FE-6 MPC Power Up 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:20-21:25 Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test	16:50-17:10	FE-4	IMS Update
17:05-18:35 CDR Physical Exercise (ARED) 17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M 5KO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-6 19:30-21:25 FE-5, FE-6 19:30-21:20 FE-5, FE-6 19:30-21:20 Pre-sleep 19:30-21:20 Reaction Self Test 19:30-21:25 MPC Power Down 21:25-21:30 FE-5 FE-5 Reaction Self Test MPC Power Down	17:05-17:35	FE-6	VO2 Stowage
17:10-17:30 FE-4 Sampling condensate upstream of CPB-K2M BKO – remove sampler, tear down setup 17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test	17:05-17:10	FE-5	PAO Hardware Deactivation
17:10-17:20 FE-5 HISD Photography 17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-19:35 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:25-21:30 FE-5 MPC Power Down 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	17:05-18:35	CDR	Physical Exercise (ARED)
17:35-18:35 FE-6 Physical Exercise T 2 18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-19:35 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:25-21:30 FE-5 MPC Power Down 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	17:10-17:30	FE-4	Sampling condensate upstream of CPB-K2M БКО – remove sampler, tear down setup
18:10-18:20 FE-5 Reinitiate LTL to the LAB1S6 CCAA 18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:25 FE-5, FE-6 Pre-sleep 19:30-19:35 MPC Power Up Pre-sleep 21:20-21:25 Reaction Self Test MPC Power Down 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	17:10-17:20	FE-5	HISD Photography
18:25-18:30 FE-4 Elektron-VM Aerosol Filter Inspection 18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-19:35 Pre-sleep 19:35-21:20 Pre-sleep 21:20-21:25 Reaction Self Test 21:25-21:30 FE-5 19:35-21:20 Reaction Self Test 21:25-21:30 FE-5 19:35-21:20 Reaction Self Test 21:25-21:30 FE-5	17:35-18:35	FE-6	Physical Exercise T 2
18:35-19:00 Daily Planning Conference (S-band) 19:00-19:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:25 FE-5, FE-6 Pre-sleep 19:30-19:35 Pre-sleep Pre-sleep 19:35-21:20 Pre-sleep Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	18:10-18:20	FE-5	Reinitiate LTL to the LAB1S6 CCAA
19:00-19:30 Evening Work Prep 19:30-21:30 FE-1, FE-2, FE-4 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:20-21:25 Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	18:25-18:30	FE-4	Elektron-VM Aerosol Filter Inspection
19:30-21:30 FE-1, FE-2, FE-6 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:20-21:25 Reaction Self Test 21:25-21:30 FE-5 Reaction Self Test 21:25-21:30 FE-6 Reaction Self Test	18:35-19:00		Daily Planning Conference (S-band)
19:30-21:30 FE-4 Pre-sleep 19:30-21:25 FE-5, FE-6 MPC Power Up 19:35-21:20 Pre-sleep 21:20-21:25 Reaction Self Test 21:25-21:30 FE-5 21:25-21:30 FE-5 21:25-21:30 FE-6	19:00-19:30		Evening Work Prep
19:30-19:35 Heaction Self Test 19:35-21:20 MPC Power Up 21:20-21:25 Reaction Self Test 21:25-21:30 MPC Power Down 21:25-21:30 FE-5 21:25-21:30 FE-6 Reaction Self Test	19:30-21:30		Pre-sleep
19:35-21:20 21:20-21:25 21:25-21:30 Pre-sleep Reaction Self Test MPC Power Down 21:25-21:30 FE-5 21:25-21:30 FE-6 Reaction Self Test	19:30-21:25	FE-5 , FE-6	
21:20-21:25 Reaction Self Test	19:30-19:35	CDR	MPC Power Up
21:20-21:25	19:35-21:20		Pre-sleep
21:25-21:30 FE-5 21:25-21:30 FE-6 Reaction Self Test	21:20-21:25		Reaction Self Test
21:25-21:30 FE-6 Reaction Self Test	21:25-21:30		MPC Power Down
21:25-21:30 FE-6	21:25-21:30		Reaction Self Test
21:30-06:00 SLEEP	21:25-21:30		
	21:30-06:00		SLEEP

Notes:

- 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC
- See OSTP for references to US activities
 Pre-sleep ops: daily food prep, dinner, pre-sleep -- End of Radiogram