Radiogram No. 7242u	Form 24 for 03/13-03/14/08
Nadiodiani No. 12424	1 01111 24 101 03/ 13-03/ 14/00

Radiogram No.		Form 24 for 03/13-03/14/08	
GMT	CREW	ACTIVITY	
20:30-20:40	FE-2, CDR	Morning Inspection	
20:30-20:35	FE-1	HAM Radio deactivation in SM	
20:35-20:40		Morning Inspection	
20:35-21:05	CDR	Post-sleep	
20:40-21:10	FE-2, FE-1		
21:05-21:55	CDR	BREAKFAST	
21:10-22:00	FE-2, FE-1		
21:10-22:20	FE-2-16	EVA - Hygiene Break/Prebreathe	
21:55-22:20	CDR	EVA - pause/pre-breathe/transfer hatch closure	
22:00-22:20	FE-1	Prep for Work	
22:00-22:30	FE-2	Piepioi vvoik	
22:20-23:50	CDR, FE-2-16	Preparation for EVA1	
22:20-22:30	FE-1	PLANTS-2. Data downlink	
22:30-23:30	L-1	Search for Airducts to assemble Soyuz (DC1) Ventilation	
23:13-23:22	FE-1	Morning reports. RS3 Tagup (VHF)	
22:30-22:35	FE-2	Payload Status Check	
23:15-23:45	FE-2	Position SSRMS for EVA1 support	
23:30-23:40	FE-1	PLANTS-2. Data downlink (terminate)	
23:45-00:40	FE-2	Physical Exercise (TVIS)	
23:50-00:05	CDR, FE-2-16	EMU purge	
00:05-00:55	CDK, FE-2-10	EMU pre-breathe before EVA	
00:10-00:25	FE-1	Verify ИП-1 Flow Meter Positions	
00:25-01:25	L-1	Physical Exercise (VELO + RED), day 3	
00:40-01:35	FE-2	Physical Exercise (CEVIS)	
00:55-01:25	CDR, FE-2-16	Crew Lock Depress	
01:25-01:30	FE-2-16	Crew Lock Depress	
01:25-02:55	FE-1	Physical Exercise (TVIS), day 3	
01:25-02:55	CDR	Physical Exercise (RED)	
01:30-01:50	FE-2-16	Crew Lock egress	
01:35-02:35	FE-2	LUNCH	
01:50-02:10	FE-2-16	Prep for EVA	
02:10-03:25	1 L Z 10	Preparation for JLP unberth	
02:35-03:05	FE-2	CW/RW sample transfer	
02:55-03:55	FE-1	LUNCH	
02:55-03:00		VOA power down	
03:00-03:05	CDR	N2 Transfer Start	
03:05-04:05		Physical Exercise (CEVIS)	
03:05-06:00	FE-2	SSRMS EVA1 support	
03:25-05:25	FE-2-16	Installation of OTCM on SPDM Arm2	
03:55-05:55	FE-1	SM Ventilation System Preventive Maintenance (BB1PO, BB2PO)	

04:05-05:05	CDD	LUNCH	
05:05-05:50	CDR	N2 Transfer Start	
05:25-06:45	FE-2-16	Installation of OTCM on SPDM Arm1	
05:55-06:00	CDR	Transfer TVIS/RED/CEVIS/HRM data to MEC	
05:55-06:30	FE-1	GCP-TM file dump application troubleshooting	
06:00-06:15	CDR	CBCS powerup	
06:35-06:40	5-06:40 FE-2	EVA Glove Photo Setup	
06:40-07:20		SODF deploy	
06:45-07:10	FE-2-16	SPDM assembly prep	
07:10-07:35		EVA1 Cleanup	
07:20-07:25	FE-2	Verify Node2 nadir CBM Pre-Mate Status	
07:25-08:05	FE-1	СОЖ Maintenance	
07:25-07:55	FE-2	Prep for Work	
07:35-07:50	FE-2-16	EVA A/L ingress	
07:50-07:55	CDR, FE-2-16	Crew Lock ingress before repress	
07:55-08:10		Crew Lock Repress	
07:55-08:10	FE-2	NODE 2 (stage 1) nadir CBM bolt capture	
08:05-08:25	FE-1	IMS update	
08:10-09:40	CDR,FE-2-16	Post-EVA ops	
08:15-09:00	FF 0	NODE 2 - JPL (stage 2) nadir CBM bolt capture	
09:00-09:05	FE-2	Full latching of Node 2 Hatch	
09:00-10:00	FE-1	Evening work prep	
09:10-09:40	FE-2	Removal of Centerline Berthing Camera System (CBCS)	
09:40-09:55	FE-2-16	Daily Food Prep	
09:40-10:00	FE-2	SSRMS OBSS Pre-Grapple Maneuver	
09:40-09:45	CDR	EVA photo downlink	
09:45-10:00	CDR	Pre-sleep	
09:55-10:10	FE-2-16	Private Medical Conference (Ku + S-band)	
10:00-10:30	FE-1, FE-2	Daily Food Prep	
10:00-11:15	CDR	Node2-JPL leak check	
10:10-10:25	FE-2-16	Daily Food Prep	
10:25-10:55	FE-2-10	DINNER	
10:30-11:00	FE-1, FE-2	DINNER	
10:55-12:00	FE-2-16		
11:00-12:00	FE-2, FE-1	Pre-sleep	
11:15-11:30	CDR		
11:30-12:00	ODIC	DINNER	
12:00-20:30		SLEEP	
Task List	FE-1	ТБУ (Universal Bioengineering Thermostat). Temperature check	
		PLANTS-2. Payload Status Check and Photography	

Notes:

- See OSTP for references to US activities.
 SM Window #9 shutter opening is at crew discretion w/ Report to MCC

End of Radiogram