Radiogram No. 8221u Form 24 for 07/25/08 Installation of FGB Enclosures. Deactivation of REGUL String 3

GMT	CREW	ACTIVITY
06:00-06:10	Ì	Morning Inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Prep for Work
07:45-08:00		Daily Planning Conference (S-band)
08:00-08:15		Prep for Work
08:15-08:20	FE-2	Install tray for Shear experiment
08:20-08:35		ISS Crew and ГОГУ (RSA Flight Control Team) Weekly Conference (S-band)
08:35-09:25	CDR	PLASMA CRYSTAL-3 PLUS. Evacuating Plasma Chamber and Testing Hardware
08:35-08:45	FE-2	Deactivation of OGS Water Delivery System (WDS)
08:35-09:15	FE-1	Microbial surface sample collection (To+2)
08:45-10:15	FE-2	Physical Exercise (RED)
09:15-10:15	FE-1	Physical Exercise (CEVIS)
09:25-10:15	CDR	PLASMA CRYSTAL. S/W loading
10:15-10:35	CDIC	PLASMA CRYSTAL-3 PLUS. Log-file downlink from Experimental Unit
10:15-12:45	FE-1	Installation of enclosures in zone 36 (panels 114, 115). Tagup with specialists (S-band, as necessary)
10:15-11:15	FE-2	Physical Exercise (CEVIS)
10:35-12:05	CDR	Physical Exercise (TVIS), day 2
11:15-11:35	FE-2	Dectivation of Oxygen Generator (OGS)
11:35-12:35		H2 reconfiguration
12:05-12:45	CDR	СОЖ maintenance
12:35-12:45	FE-2	MEC Hard Drive Reload, Part 4
12:45-13:45		LUNCH
13:45-14:55		OBT on emergency response to ISS depress (S-band)
14:55-15:10	CDR, FE-1	IMS tagup (S-band)
14:55-16:35	FE-2	
15:10-16:40	FE-1	Installation of enclosures in zones 405 (panel 215). Tagup with specialists (S-band, as necessary)
15:10-15:15	CDR	PLASMA CRYSTAL-3 PLUS. Leak Check 1
15:15-16:30	CDR	SM Ventilation System Preventive Maintenance Group
16:40-17:00		Conference for Emergency Response to Rapid Depress On-board ISS (S-band)
17:00-18:30	FE-1	Physical Exercise (TVIS), day 2
17:00-17:20	CDR	
17:00-17:30	FE-2	BLB. Changeout
17:20-18:20	CDR	Physical Exercise (CEVIS)
17:30-17:40	FE-2	Inspection of RED and additional equipment
17:40-17:55		Start Filling CWC from the Lab Condensate Tank

	-1	
17:55-18:20		Ops LAN - set up equipment to reload
18:20-18:40		Crew OBT, Ops LAN overview
18:20-18:25	CDR	TVIS Bearings Weekly Maintenance
18:25-18:30		Transfer TVIS, RED, and HRM data to MEC
18:30-18:55	CDR, FE-1	Prep for Work
18:40-18:55	FE-2	Terminate filling CWC from Lab Condensate Tank
18:55-19:10		Daily Planning Conference (S-band)
19:10-19:15	CDR	PLASMA CRYSTAL-3 PLUS. Leak check 2
19:10-19:40	FE-1, FE-2	DINNER
19:15-19:45	CDR	
19:40-20:10	FE-1, FE-2	Daily Food Prep
19:45-20:15	CDR	
20:10-20:35	FE-1, FE-2	Pre-sleep
20:15-20:35	CDR	
20:35-20:55		Flight Director / ISS Crew Tagup (Ku + S-band)
20:55-21:30	FE-1	Pre-sleep
20:55-21:25	CDR, FE-2	
21:25-21:30	CDR	PLASMA CRYSTAL-3 PLUS. Turbo pump deactivation
21:25-21:30	FE-2	Log entry reminder
21:30-06:00		SLEEP
Task List	FE-1	PLANTS-2. Data downlink

- SM Window #9 shutter opening is at crew discretion with Report to MCC / r/g 6083, 6004
 See OSTP for references to US activities.
 Tagup with specialists during activities with ΠK-3 (S-band)
 No access to OCA from 00:30 through 01:45

- End of Radiogram