ПГО-SM PEV Replacement In FGB. ВД-СУ Mode Deactivation/Activation And БИТС Power Off/On.

GMT	CREW	ACTIVITY
06:00-06:10	CDR, FE-1,FE- 2 , FE-5,FE-6	Morning Inspection
06:00-06:10	FE-4	Morning Inspection. Inspection of CM-Y connector on MHP-HC separator pump behind ACY panel 139. SM ΠCC [Caution & Warning Panel] Test
06:10-06:40		Post-sleep
06:40-07:30	CDR, FE-4 , FE-5,FE-6	BREAKFAST
06:40-07:30	FE-1,FE-2	Breakfast
07:30-07:40	FE-6	Glove Box (MSG) Activation
07:30-07:50	CDR, FE-1,FE- 2 , FE-4 ,FE-5	Work Prep
07:40-07:50	FE-6	Work Prep
07:50-08:15		Daily Planning Conference (S-band)
08:15-08:45	FE-2	Auxiliary Laptop Anti-Virus Update
08:15-08:45	FE-5	Station Support Computer (SSC) Wireless Outage Preparation
08:15-08:25	FE-6	Work Prep
08:15-08:25	FE-1	URAGAN. FSS PL Battery Charge (terminate)
08:15-09:45	CDR	Physical Exercise (ARED)
08:25-08:30	FE-4	Comm Config Before Plazmennyi Kristall-3 Experiment
08:25-08:35	FE-6	EHS Air Quality Monitoring (AQM) Start
08:30-09:00	FE-4	Plazmennyi Kristall. Electrical Connections Configuration and Video Hard Drive Installation. <i>Tagup with specialists (S-band)</i>
08:40-08:50	FE-6	Connecting DCP Power Cable
08:45-09:45	FE-5	Physical Exercise (T2)
08:45-10:15	FE-2	Monitoring the condition of RS structural element surfaces using MBΠ device. Preparation. <i>Tagup with specialists (S-band)</i>
08:50-09:00	FE-1	BAR. TTM Charge Start
09:00-10:00	FE-1	Physical Exercise (VELO), Day 1
09:00-09:40	FE-6	SLICE Ops Prep
09:00-09:20	FE-4	Plazmennyi Kristall. Software Installation. <i>Tagup with specialists (S-band, VHF)</i>
09:20-09:30	FE-4	ISS-MCC TV. Plazmennyi Kristall-3 PLUS. Video Setup and Downlink. Tagup with specialists (S-band, VHF)
09:30-09:50	FE-4	Plasma Crystal-3 Plus. Monitoring TV signal on display
09:40-10:20	FE-6	SLICE Operations
09:45-11:15	FE-5	Physical Exercise (ARED)
09:45-10:45	CDR	Physical Exercise (T2)
09:50-09:55	FE-4	Restore nominal comm configuration
10:00-11:50	FE-1	RUSALKA Setup, photo/video, data copy, and closeout ops. <i>Tagup with specialists as necessary (S-band)</i>

10:15-11:45	FE-2	Physical Exercise (TVIS), Day 1
10:20-10:30	FE-6	SPICE Burner Exchange
10:30-11:10	FE-6	SLICE Operations
10:45-11:35	FE-4	Plazmennyi Kristall-3. Closeout Ops
11:10-11:20	FE-6	SLICE Flash Card Exchange
11:15-11:25	CDR	Relocating Ziploc bag containing old hardware that doesn't require urgent access
11:15-12:30	FE-5	ICV Monitoring Start
11:25-11:35	CDR	ICV Start Operator Assistance
11:35-12:35	FE-4	Physical Exercise (TVIS), Day 1
11:35-12:35	FE-6	Physical Exercise (T2)
11:35-12:25	CDR	WRM take Lab condensate tank samples and start draining
12:00-13:00	FE-1	URAGAN Observations and Photos using Photo Spectrum System (ФСС) PL
12:25-13:25	CDR	LUNCH
12:30-12:40	FE-5	ICV - 10-Minute Resting Event Alternate
12:30-12:40	FE-2	Replacing ИК0501 CO2 Filter Unit (БФ). <i>Install #129 (00054194R, CM1PO_4_449_1, Bag 354-1 (00038525R)). Discard the removed unit. Update IMS</i>
12:35-13:35	FE-4 ,FE-6	LUNCH
12:40-13:40	FE-5	LUNCH
12:40-12:55	FE-2	Verify ИП-1 sensor positions
13:00-14:00	FE-1,FE-2	LUNCH
13:25-13:35	CDR	WRM Terminate Lab Condensate Tank Draining
13:35-14:15	CDR	T2 Quarterly Maintenance
13:35-13:55	FE-6	SLICE Fan Checkout
13:40-14:10	FE-5	SSC Wireless Outage Reconfigure
13:40-14:40	FE-4	ΠΓΟ-SM PEV replacement in FGB - preparation. <i>Tagup with specialists</i> (S-band)
13:55-14:05	FE-6	SLICE Video Tape Exchange
14:00-15:20	FE-1,FE-2	BAR Experiment. Tagup with specialists (S-band)
14:05-14:20	FE-6	Journal Entry
14:15-14:25	CDR	CIR Photo/TV Prep
14:15-14:25	FE-5	WRS Water Sample Analysis
14:20-14:30	FE-6	RWS Cupola Crew Restraint (CCR) Removal
14:25-14:40	CDR	CIR Front End Cap Open
14:30-14:45	FE-5,FE-6	SSRMS Procedure Review
14:40-15:00	CDR	CIR Front End Cap Open
14:40-14:50	FE-4	On MCC Go Demate PEV TLM connector I Tagup with specialists (S-band)
14:45-15:35	FE-6	ICV Monitoring Prep
14:45-15:15	FE-5	Urine Monitoring System (UMS) Gather
14:50-16:50	FE-4	ПГО-SM PEV replacement in FGB. Tagup with specialists (S-band)
15:00-17:35	CDR	MDCA Fuel Reservoir Replacement
15:15-15:25	FE-5	Urine Monitoring System (UMS) Reference Material Review

15:20-16:50	FE-1	Physical Exercise (TVIS), Day 1
15:25-17:25	FE-5	US Sound Level Meter (SLM) Setup and Acoustic Survey
15:35-15:45	FE-6	Glove Box (MSG) Powerdown
15:40-16:40	FE-2	Physical Exercise (VELO), Day 1
15:45-15:55	FE-6	EHS - Air Quality Monitor (AQM) End
15:55-17:25	FE-6	Physical Exercise (ARED)
16:40-18:40	FE-2	Stereo photography of the scratch on MRM2 Вл1 window. <i>Tagup with specialists (S-band)</i>
16:50-17:00	FE-4	On MCC Go Mate PEV electrical connector
17:00-17:30	FE-4	ΠΓΟ-SM PEV replacement in FGB - closeout ops. <i>Tagup with specialists (S-band)</i>
17:00-17:30	FE-1	SEINER Ocean Observations
17:25-18:15	FE-5,FE-6	SSRMS maneuver
17:30-18:10	FE-1	СОЖ Maintenance
17:30-18:50	FE-4	Physical Exercise (VELO), Day 1
17:35-18:00	CDR	CIR Front End Cap Close
18:00-18:15	CDR	CIR Front End Cap Close
18:10-18:30	FE-1	IMS Update
18:15-18:30	CDR	Journal Entry
18:15-18:25	FE-6	RWS Cupola Crew Restraint (CCR) Removal
18:15-18:25	FE-5	TOCA Data Recording And Downlink
18:25-18:35	FE-6	Disconnect Display and Control Panel (DCP) Power Cable
18:25-18:50	FE-5	Evening Work Prep
18:30-18:50	CDR, FE-1	Evening Work Prep
18:35-18:50	FE-6	Evening Work Prep
18:40-18:50	FE-2	Evening Work Prep
18:50-19:15		Daily Planning Conference (S-band)
19:15-19:30		Evening Work Prep
19:30-19:35	CDR	P/TV Playback Start
19:30-21:20	FE-1	Pre-sleep
19:30-21:30	FE-2,FE-4 , FE-5,FE-6	Pre-sleep
19:35-21:25	CDR	Pre-sleep
21:20-21:30	FE-1	RUSALKA. Battery charge (start)
21:25-21:30	CDR	P/TV Playback End
21:30-06:00		SLEEP
	FF 4 FF 6	Preparation of reports for Roskosmos site
Task List	FE-1,FE-2, FE-4	URAGAN. Observations and Photography
	L-4	ECON. Observations and Photography

Notes:

- SM Window #9 shutter opening is at crew discretion w/ Report to MCC
 See OSTP for references to US activities
 Pre-sleep ops: daily food prep, dinner, pre-sleep
 End of Radiogram