Form 24 for 01/12/2011

Radiogram No. 5085u PREPARATION FOR EVA. PLASMA CRYSTAL

GMT	CREW	ACTIVITY
06:00-06:10	CDR, FE-2 , FE-5, FE-6	Morning Inspection
06:00-06:05	FE-1	PLASMA CRYSTAL ПК-3 PLUS EB Turbo-Pump Activation
06:00-06:05	FE-4	Elektron-VM Aerosol Filter Inspection
06:05-06:30		Post-sleep
06:05-06:10	FE-1	Morning Inspection
06:10-06:40	CDR, FE-1 , FE-2 , FE-5, FE-6	Post-sleep
06:30-07:30	FE-4	SPRUT-2 Experiment Ops
06:40-07:30	CDR, FE-1 , FE-2 , FE-5, FE-6	BREAKFAST
07:30-07:50		Daily Planning Conference (S-band)
07:50-08:10	FE-1, FE-2	Work Prep
07:50-08:50	FE-4	BREAKFAST
07:50-08:00	CDR	Work Prep
07:50-07:55	FE-6	WHC UPA Config
07:50-07:55		Work Prep
07:55-08:30	FE-5	Scheduled Maintenance of Compound Specific Analyzer- Combustion Products (CSA-CP)
07:55-08:00	FE-6	Work Prep
08:00-09:30	CDR	Periodic Fitness Evaluation - Nom Ops (subject)
08:00-08:05	FE-6	ISS HAM Radio Setup in Service Module
08:05-08:20	FE-0	ISS HAM Radio Session from SM
08:10-08:50	FE-2	СОЖ Maintenance
08:20-08:35	FE-6	Work Prep
08:30-08:55	FE-5	Environmental Health System (EHS) CSA-CP Calibration
08:35-09:05	FE-6	Periodic Fitness Evaluation - Nom Ops (assistance)
08:50-09:05	FE-4	Work Prep
08:55-09:05	FE-5	FIR Alignment Guide Removal
08:55-09:05	FE-2	Charging Progress 408 CpΠK Section 2 with N2
09:00-09:05		Comm config prior to PLASMA CRYSTAL-3 experiment
09:05-09:25	FE-1	PLASMA CRYSTAL Hardware Activation and Experiment Start. <i>Tagup with specialists (S-band)</i>
09:05-09:10	FE-6	SLAMMD Setup
09:05-09:20	FE-5	Private Psychological Conference
09:05-11:15	FE-2, FE-4	DC1 and ΠxO preparation for EVA
09:10-09:20	FE-6	SLAMMD Body Mass Measurement
09:20-09:40		BCAT5 Camera Check Without SSC
09:20-10:20	FE-5	Physical Exercise T 2

00.05 00 45	FF 4	TV (ISS-MCC) PLASMA CRYSTAL. Start and Monitor the Experiment. Tagup
09:25-09:45	rt-1	with specialists (S-band)
09:30-09:40	CDR	SLAMMD Body Mass Measurement
09:40-09:45		Payload MPC Power On
09:40-11:10	FE-6	Physical Exercise (ARED)
09:45-09:55	CDR	CIR Alignment Guide Removal
09:50-10:50	FE-1	Physical Exercise (VELO), Day 3
09:55-10:25	CDR	Psychological Evaluation Program (WinSCAT)
10:25-10:45		HMS Visual Testing Activity
10:45-10:50	FE-5	ISS HAM Radio Setup in Service Module
10:45-11:00	CDR	MI Handle Fastener 1 Installation to MI Handle
10:50-11:10	FE-1	PLASMA CRYSTAL Experiment Termination
10:50-11:05	FE-5	ISS HAM Radio Session from SM
11:00-11:20	CDR	BCAT-5 Sample 10 Photography
11:05-11:15	FE-5	SLAMMD Body Mass Measurement
11:10-11:20	FE-6	FIR Photo/Video Setup
11:10-11:40		PLASMA CRYSTAL. Copying Data from the Hard Drive. Tagup with Specialists (S-band)
11:15-12:45	FE-2	Physical Exercise (TVIS), Day 3
	FE-4 , FE-5, FE-6	CHeCS OBT
11:30-13:00	CDR	Physical Exercise (ARED)
11:40-11:45		Comm system reconfig after running PLASMA CRYSTAL-3 experiment
11:45-12:00	FE-1	Verify ИΠ-1 Flow Meter Configuration
12:00-12:20		IMS Update
12:20-12:40	FE-6	SLAMMD Equipment Stow
	FE-4, FE-5, FE-1 assists	Study of Cardiac Bioelectric Activity At Rest. To=12:34 . <i>Tagup with specialists</i> (VHF)
12:40-12:55	FE-6	SLAMMD Equipment Stow
13:00-14:00		LUNCH
14:00-14:05	CDR	Payload MPC Power Off
14:00-15:20	FE-4	DC1 and ΠxO Preparation for EVA
14:00-14:10	FE-6	ARIS Range Test Monitoring
14:00-15:30	FE-1	Connecting Onboard Cables to PCE (МБРЛ). Tagup with specialists (S-band)
14:00-17:20		DC1 and ΠxO Preparation for EVA
	FE-5	Setup for Robotics OBT
	CDR	MI-CORE-CLEANING2
14:10-14:15		CGBA 5 Bioprocessor Status Check
14:15-14:30	FE-6	PCS Laptop Connect
	FE-5	Photo/TV Setup for ROBoT Ops
	FE-5, FE-6	Robotics - MSS Proficiency Training
	FE-4	Physical Exercise (TVIS), Day 4
		· , , , ,
15:35-16:35	FE-1	Install and connect ATV Hand Controller in ISS SM. Tagup with specialists (S-

		band)
16:05-17:05	CDR	Physical Exercise T 2
16:25-16:35		Robotics - MSS Proficiency Training
16:35-16:50		Teardown ROBoT after Training Session
16:35-16:45		КОБ2 4ГБ4 Half-Coupling Shell Coolant Leak Check
16:35-16:50		Private Psychological Conference
16:45-18:15		Physical Exercise (TVIS), Day 3
16:50-16:55		Stow Video Equipment Used during ROBoT Ops
16:50-17:50		Physical Exercise (VELO), Day 4
16:50-17:10		HMS Vision Test
16:55-17:10	FE-5	FSL FCE locking at the end of scientific operations
17:05-17:25		EXPRESS Rack 6 Laptop Configuration
17:10-18:10	FE-6	Physical Exercise T 2
17:15-18:45	FE-5	Physical Exercise (ARED)
17:20-17:45	FE-2	Evening Work Prep
17:30-17:50	CDR	Binary Colloid Alloy Test - Crystal Photography
17:45-18:45	FE-2	Physical Exercise (VELO), Day 3
17:50-18:00	000	Closing USOS Window Shutters
18:00-18:15	CDR	Private Psychological Conference
18:10-18:20	FE-6	T2 Snubber Arm Inspection
18:10-18:15	FE-4	Elektron-VM Aerosol Filter Inspection
18:15-18:25	CDR	FIR Alignment Guide Installation
18:15-18:45	FE-1, FE-4	Evening Work Prep
18:20-18:25	FE-6	
18:25-18:45	CDR, FE-6	HTV Conference
18:45-19:10		Daily Planning Conference (S-band)
19:10-19:30	FE-5, FE-6	Evening Work Prep
19:10-19:25	CDR	Evering Work Frep
19:10-19:30	FE-1, FE-2, FE-4	Pre-sleep
19:25-19:30	CDR	MPC Power Up
19:30-19:50	CDR, FE-2 , FE-4 , FE-5, FE-6	Crew conference with Astronaut Office
19:30-19:40	FE-1	
19:50-21:25	CDR	Pre-sleep
19:40-19:55	FE-1	On MCC GoMate PCE, ATV Control Panel and БУАП Telemetry Connectors to БИТС2-12
19:50-21:30	FE-2 , FE-4 , FE-5, FE-6	Pre-sleep
19:55-21:15	FE-1	
21:15-21:25		Check Secondary Combustion Unit Temperature After Elektron-VM Activation
21:25-21:30	CDR	MPC Power Down

	FE-1	PLASMA CRYSTAL ПК-3 PLUS Experiment Box Turbo Pump Deactivation
21:30-06:00		SLEEP

Notes:

- SM Window #9 shutter opening is at crew discretion w/ Report to MCC
 See OSTP for references to US activities
 Pre-sleep ops: daily food prep, dinner, pre-sleep
 End of Radiogram