Radiogram No. 9768u Form 24 for 02/07/05

Removal of Satellite Navigation Equipment ACH-2401-2. Installation of Navigation Receiving Module (ΗΠΜ).

GMT	CREW	ACTIVITY
06:00-06:05	FE -1	PLASMA CRYSTAL-3. Pump activation
06:00-06:10	CDR FE -1	Morning inspection
06:05-06:10		
06:10-06:40	Ì	Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45	-	Prep for work
07:45-08:00		Daily planning conference (S-band)
08:00-08:40	FE -1	PLASMA CRYSTAL-3. Experiment set up. Tagup w/ specialists (S-band)
08:00-08:10	İ	Prep for work
08:10-08:40	CDR	Defibrillator checkout
08:40-09:40		Preparation of personal hygiene items for disposal
08:40-09:15	FE -1	TV (ISS-MCC) PLASMA CRYSTAL-3. Experiment ops (start). Tagup w/ specialists (S-band)
09:15-09:55		Atmosphere purification filter (A2) size definition
09:40-10:40	CDR	Completing bags with flight equipment
10:05-10:15	FF 4	PLASMA CRYSTAL-3. Experiment ops (end)
10:15-12:15	=FE -1	CARDIOCOG-Execute Experiment_10. Tagup w/specialists.(S-band)
10:40-11:10	İ	CDM alkaline battery transfer to discharged battery container
11:25-12:10	CDR	On-orbit RED calibration.
12:10-13:40		Physical Exercise (RED)
12:15-13:45	FE -1	Physical Exercise (TVIS), day 4
13:40-13:45	CDR	Calldown of TEPC display data
13:45-14:45		LUNCH
14:45-16:15	FE -1	ACH-2401-2 unit removal. Tagup w/ specialists (S-band
14:45-16:10	CDR	LAB1P4 rack clean up
16:10-16:30	CDR	IMS file prep
16:15-17:15	FE -1	Search and installation of Navigation Receiving Module (HΠM-1, 2, 3, 4) equipment. Tagup w/specialists.(S-band)
16:30-17:00	CDR	СОЖ maintenance
17:15-18:15	CDR	Physical Exercise (TVIS)
17.15-16.15	FE -1	Physical Exercise (VELO + Force Loader/ 1), day 4
18:15-18:20	CDR	TVIS/RED/HRM data transfer to MEC
18:15-18:25	FE -1	Daily plan review
18:20-18:25	CDR	
18:25-18:40		Daily planning conference (S-band)
18:40-19:00		Daily plan review
19:00-19:05	CDR	Connection of cable-insert to LTL
19:00-19:30	FE -1 CDR	Report prep
19:05-19:30		Troport prop

19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30	CDR	Pre-sleep
20:30-21:25	FE -1	1 16-sieep
21:25-21:30		PLASMA CRYSTAL-3. Pump deactivation
21:30-06:00		SLEEP
Task List	FE -1	PLANTS-2. Hardware monitoring

Note: See OSTP for references to US activities End of radiogram