Radiogram No. 2539u Form 24 fo Locating Tools and Equipment for EVA.

Transfering h/w marked for disposal to TKF 419 Form 24 for 06/07/2013

| TIME        | CREW   | ACTIVITY  |
|-------------|--|---|
| 06:00-06:10 | CDR  | Morning Inspection. Laptop RS2(1) Reboot  |
|             | FE-2   | Morning Inspection. RSS1, RSS2 Reboot   |
|             | FE-4   | Morning Inspection. SM ΠCC (Caution & Warning Panel) Test                         |
| 06:00-06:10 | FE-3   | Morning Inspection  |
| 06:00-06:05 | FE-5   | Reading REMINDER  |
| 06:00-07:00 | FE-6   | BIOME- Sampling Operations  |
| 06:05-06:10 | FE-5   | PROK - Urine Sample Collection  |
| 06:10-06:40 | CDR, FE-2,<br>FE-4                           | Post-sleep  |
| 06:10-06:45 | FE-3   | Post-sleep  |
| 06:10-06:30 | FE-5   | HRF Urine Sample Collection   |
| 06:30-06:35 | FE-5   | HRF - Urine sample insertion into MELFI   |
| 06:35-06:40 | FE-5   | Reminder to the crew about Circadian Rhythms experiment                           |
| 06:40-07:30 | CDR, FE-2,<br>FE-4                           | BREAKFAST   |
| 06:40-07:05 | FE-5   | HRF Blood Draw  |
| 06:50-07:05 | FE-3   | HRF Blood Draw  |
| 07:00-07:05 | FE-6   | HRF - Urine Sample MELFI Insertion  |
| 07:05-07:30 | FE-3   | BREAKFAST   |
| 07:05-07:15 | FE-5   | Morning Inspection  |
| 07:05-07:15 | FE-6   | PROK - Urine Sample Collection  |
| 07:15-07:30 | FE-5   | HRF Refrigerated Centrifuge Configuration   |
| 07:15-07:30 | FE-6   | Morning Inspection  |
| 07:30-07:55 |  | Daily Planning Conference (S-band)  |
| 07:55-08:05 | <b>CDR</b> , <b>FE-2</b> , FE-3, <b>FE-4</b> | Work Prep   |
| 07:55-08:05 | FE-6   | Post-sleep  |
| 08:00-08:05 | FE-5   | HRF - Blood sample removal from centrifuge and its deactivation                   |
| 08:05-08:20 | CDR, FE-2,<br>FE-3, FE-4,<br>FE-6            | ISS Crew and ГОГУ (RSA Flight Control Team Management) Weekly Conference (S-band) |
| 08:05-08:10 | FE-5   | HRF - Urine Sample MELFI Insertion  |
| 08:10-08:15 | FE-5   | BIOME - Survey Questionnaire  |
| 08:15-08:45 | FE-5   | Post-sleep  |
| 08:20-08:35 | CDR, FE-2,<br>FE-4                           | IMS Tagup (S-band)  |
| 08:20-08:30 | FE-3   | Work Prep   |
| 08:20-08:50 | FE-6   | Post-sleep  |

| 08:35-10:05 | CDR                | TKΓ 419 (Aft) Stowage and IMS Ops   |
|-------------|--------------------|---|
| 08:35-11:35 | FE-2, FE-4         | Locating EVA hardware and tools Tagup with specialists (S-band)   |
| 08:35-10:05 | FE-3               | Physical Exercise (ARED)  |
| 08:45-09:35 | FE-5               | BREAKFAST   |
| 08:50-09:25 | FE-6               | BREAKFAST   |
| 09:25-10:10 | FE-6               | BIOME - Hardware Setup and Sampling   |
| 09:35-10:10 | FE-5               | Work Prep   |
| 10:05-10:15 | CDR                | TKΓ 419 (Aft) Packing Completion Status Report (S-band)   |
| 10:05-10:15 | FE-3               | CIR - Hardware Setup  |
| 10:10-10:20 | FE-5               | WRS Water Sample Analysis   |
| 10:10-10:15 | FE-6               | HRF - Urine Sample MELFI Insertion  |
| 10:15-11:15 | CDR                | Physical Exercise (ARED)  |
| 10:25-12:25 | FE-3, FE-6         |   |
| 10:25-11:15 | FE-5               | ISS 36 Crew Handover  |
| 11:15-12:35 | CDR                | Removal of two Handles from TKΓ 416 Front Hatch Cover. TΓΚ 419P. Stow in ΠΡИΗΑДЛЕЖНОСТИ CmA 11Φ732.Γ4000A1-30 kit (CM1ΠρΚ_1, next to transfer hatch) docking mechanism (CτM) installation |
| 11:15-12:15 | FE-5               | SKIN B - Equipment setup nominal ops  |
| 11:35-12:35 | FE-2               | TΓΚ 419P (AO) docking mechanism (CτM) installation  |
| 11:35-13:05 | FE-4               | Physical Exercise (VELO), Day 3   |
| 12:15-12:25 | FE-5               | Crew Prep for PAO   |
| 12:25-12:35 | FE-3, FE-5         | PAO Hardware Setup  |
| 12:25-12:50 | FE-6               | BSA battery charge - start  |
| 12:35-13:35 | FE-2               | Physical Exercise (VELO), Day 3   |
| 12:35-13:15 | CDR                | СОЖ Maintenance   |
| 12:35-13:35 | FE-3               | MSPR - Combustion Chamber (CC) Leak Check   |
| 12:35-12:55 | FE-5               | PAO Event   |
| 12:50-13:50 | FE-6               | LUNCH   |
| 12:55-13:55 | FE-5               | LUNCH   |
| 13:05-13:25 | FE-4               | 24-hour BP monitoring (terminate)   |
| 13:30-14:30 | CDR, FE-4          | LUNCH   |
| 13:35-14:35 | <b>FE-2</b> , FE-3 | LUNCH   |
| 13:50-14:00 | FE-6               | PROK - Controlled Diet Log  |
| 13:55-14:05 | FE-5               | TOCA 2 Data Recording   |
| 14:00-15:00 | FE-6               | Crew time for ISS adaptation and orientation  |
| 14:05-14:15 | FE-5               | PROK - Diet Log and Log Photo   |
| 14:25-15:25 | FE-5               | Crew time for ISS adaptation and orientation  |
| 14:30-14:35 | CDR                | MRM2 comm config to support voice comm during experiment  |
| 14:30-14:40 | FE-4               | URAGAN. Photo Spectral System Battery Charge (start)  |
| 14:35-15:45 | CDR                | PLAZMENNIY KRISTALL. Plasma Chamber Leak Check. Tagup with  |

|             |                                   | specialists (S-band)  |
|-------------|-----------------------------------|---|
| 14:35-16:05 | FE-2                              | Replacing E-K container and hose in ACY <i>Install № 1206097</i> (00059876R, CM1PO_1_138_1). Removed hw - mark for disposal on TKF №419. update IMS |
| 14:35-15:35 | FE-3                              | RGN-REC TK – Transfer and Replacement   |
| 14:40-15:00 | FE-4                              | Reconfigure Regul-Packet to Regul-OS Set 2  |
| 15:00-16:00 | FE-4                              | Crew time for ISS adaptation and orientation  |
| 15:20-15:40 | FE-6                              | BIOME - Setup   |
| 15:25-16:55 | FE-5                              | Physical Exercise (ARED)  |
| 15:40-16:40 | FE-6                              | Physical Exercise (CEVIS)   |
| 15:45-16:20 | CDR                               | PLASMA CRYSTAL Software Installation. Tagup with specialists (Sband)  |
| 15:50-16:50 | FE-3                              | Physical Exercise T2  |
| 16:05-17:05 | FE-4                              | БД-2 Exercise (passive mode)  |
| 16:20-16:55 | CDR                               | PLAZMENNYI KRISTALL-3. Data Copy and Log File Dump from Experiment Box. <i>Tagup with specialists (S-band)</i>                                      |
| 16:40-16:50 | FE-6                              | BIOME- Sampling Operations  |
| 16:50-17:05 | FE-3                              | RGN - Initiate drain into EDV   |
| 16:50-16:55 | FE-6                              | HRF - Urine Sample MELFI Insertion  |
| 16:55-17:55 | FE-5                              | Physical Exercise T2  |
| 16:55-17:00 | CDR                               | Restore Nominal Comm Configuration  |
| 16:55-18:25 | FE-6                              | Physical Exercise (ARED)  |
| 17:00-17:30 | CDR                               | Evening Work Prep   |
| 17:10-18:20 | FE-4                              | URAGAN. Observation and Photography using Photo Spectral System (ΦCC). <i>Tagup with specialists</i> ( <i>S-band</i> )                              |
| 17:20-17:35 | FE-3                              | RGN - Terminate drain into EDV  |
| 17:35-17:45 | FE-2                              | ON MCC GO Filling up CpΠK TΓK 419 (AO) Section 2 with N2  |
| 17:35-17:50 | FE-3                              | MSPR - Combustion Chamber (CC) Leak Check   |
| 17:30-18:55 | CDR                               | БД-2 Exercise (passive mode)  |
| 17:50-18:50 | FE-3                              | Multi - Purpose Small Payload Rack (MSPR) Combustion Chamber (CC) Closeout  |
| 17:55-18:00 | FE-5                              | Space Headaches Weekly Questionnaire  |
| 17:55-18:55 | CDR                               | Physical Exercise T2 - day 3  |
| 18:00-18:15 | FE-5                              | BIOME - Hardware Setup for the Experiment   |
| 18:15-18:55 | FE-5                              | Thermolab - Instrumentation Ops for Circadian Rhythms   |
| 18:25-18:35 | FE-6                              | BIOME - Hardware Stow after the experiment  |
| 18:25-18:55 | FE-4                              | Fuening West Dren   |
| 18:30-18:55 | FE-6                              | Evening Work Prep   |
| 18:55-19:20 |                                   | Daily Planning Conference (S-band)  |
| 19:20-20:30 | CDR, FE-2,<br>FE-4, FE-5,<br>FE-6 | Pre-sleep   |

| 19:25-20:30 | FE-3               | Pre-sleep                                 |
|-------------|--------------------|---|
| 20:30-20:50 |                    | Flight Director / ISS Crew Tagup (S-band) |
| 20:50-21:20 | FE-3, FE-6         | Pre-sleep                                 |
| 20:50-21:25 | CDR                |   |
| 20:50-21:15 | FE-5               |   |
| 20:50-21:30 | FE-2, FE-4         |   |
| 21:15-21:20 | FE-5               | BCAT Reminder                             |
| 21:20-21:25 | FE-6               |   |
| 21:25-21:30 | FE-3               |   |
| 21:20-21:25 | FE-5               | Questionnaire REMINDER-                   |
| 21:25-21:30 | CDR                | PLAZMENNIY KRISTALL. Pressure Check       |
| 21:25-21:30 | FE-5, FE-6         | REMINDER - Reading Reminder               |
| 21:30-06:00 |                    | SLEEP                                     |
| Task List   | CDR                | IMS Update                                |
|             | CDR, FE-2,<br>FE-4 | Preparation of reports for Roskosmos site |
|             |                    | ECON-M. Observations And Photography      |

## Notes:

- 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC
- 2. See OSTP for references to US activities.
- 3. Pre-sleep ops: daily food prep, dinner, pre-sleep
- 4. Russian crew uses US exercise equipment strictly per F24 or OSTPV
- 5. Do not use ISS RS windows at 18:35 18:50 and 21:25 22:00
- 6. At high beta angles the crew powers off all Auxiliary Computer System (BKC) Laptops which are not in use
- **7. 23:00-00:30 no comm; Ku-band, OCA, IP-phone are unavailable** End of Radiogram