Radiogram No. 6628u

Form 24 for 12/01/07

TEX-20 PLASMA CRYSTAL

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection Inspection of DC1 Power Panel (БВП) Circuit Breaker [A3C]and fuses in DC1 Fuse Boxes БПП-30, БПП-36
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Prep for Work
08:00-08:05	FE-2	MPC Activation for HDTV Playback Ops
08:00-09:00	CDR	Physical Exercise (CEVIS)
09:00-10:30		Physical Exercise (RED)
09:10-10:00	FE-1	ПК-3 PLUS. Evacuation of Lines and Working Chamber in the Experimental Unit [ЭБ]. <i>Tagup (S-band)</i>
10:00-10:45		ПК-3 PLUS. Software upload. <i>Tagup</i> (S-band)
10:45-12:45		RS ISS Window Inspection and Photography. Tagup (S-band)
10:45-11:15	CDR	EMU cooling loop scrub (start)
11:30-11:50		Vestibule Leak Check Termination & Repress
11:50-12:05		Intra-Module Valve (IMV) Jumper Install
11:50-12:20	FE-2	FGB Hygiene Station Water Sampling
12:20-12:50		SSRMS checkout
12:25-12:40	CDD	EMU cooling loop scrub (terminate)
12:40-12:50	CDR	EMU Cooling Loop config
12:50-13:50	İ	LUNCH
13:50-14:20	İ	Weekly Planning Conference (S-band)
14:20-14:30	CDR	Terminate BSA battery charge
14:20-14:30	FE-1	KUBIK3. Program installation on PCMCIA card. <i>Tagup (S-band)</i> Setup and copy data
14:30-14:50	CDR	Start BSA battery charge
14:40-14:55	FE-1	Private family conference (S-band)
14:50-15:20	CDR	EMU cooling loop reconfig
14:50-15:20	FE-2	De-gassing Payload Reservoir Water to be used in EMU
14:55-15:00	FE-1	ПК-3 PLUS. Pressure monitoring. <i>Tagup</i> (<i>S-band</i>)
15:20-16:10	CDR, FE-2	SSRMS checkout
15:20-15:25	FE-1	KUBIK2. Switch data cable
16:05-16:15		KUBIK2. Data copy and thermostat deactivation close-out ops. Data downlink via 6CP-TM
16:10-16:20	FE-2	Space Station Remote Manipulator System (SSRMS) Robotic Workstation (RWS) Checkout for 1E
16:15-17:15	FE-1	Physical Exercise (VELO + RED), Day 4
16:20-16:35	FE-2	O2 level check
16:55-17:55	FE-2	Physical Exercise (CEVIS)
17:15-18:45	FE-1	Physical Exercise (TVIS), Day 4

FE-2	Physical Exercise (RED)
FE-1	ПК-3 PLUS. Pressure monitoring. <i>Tagup</i> (S-band)
	СОЖ Maintenance
CDR	LAB LTL connector hookup
	MPC Deactivation
FE-2	Transfer TVIS/RED/CEVIS/HRM data to MEC
	DINNER
	Daily food prep
CDR, FE-2	Pre-sleep
FE-1	Pre-sleep
	ΠK-3 PLUS. Turbo-pump deactivation
	SLEEP
FE-1	MATRYOSHKA-R. Monitoring Lulin-5 readings
	KUBUK3. Stowage photo
	FE-1 CDR FE-2 CDR, FE-2 FE-1

Note: 1. See OSTP for references to US activities.

2. SM Window #9 shutter opening is at crew discretion

End of Radiogram