SM KURS Testing From + X Side

GMT	CREW	ACTIVITY
06:00-06:10	CDR	Morning inspection. <i>Inspection of Circuit Breaker [A3CO]on DC1 Power Switch Panel (БВП) and fuses in DC1 Fuse Boxes БПП-30, БПП-36</i>
	FE-1	Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Work prep
08:00-08:15		Daily planning conference (S-band)
08:15-11:15	CDR	Progress 353 transfer and IMS ops
08:15-10:55	FE-1	Progress 555 transfer and two ops
10:55-11:15		SSRMS wrist joint config
11:15-12:45		Physical exercise (RED)
11:15-13:45	CDR	PROFILAKTIKA. Force Loader (HC-1) experiment. <i>Tagup with specialists</i> (S-band, VHF)
12:45-13:45	FE-1	Physical exercise (TVIS)
13:45-13:50	CDR	On MCC GO: ISS O2 repress from Progress 353 CpΠK (Oxygen Supply Facility) (start)
13:45-13:50	FE-1	Transfer TVIS, RED, and HRM data to MEC
13:50-14:50		LUNCH
14:50-15:35	FE-1	Stow first PCS 760
14:50-14:55	CDR	ISS O2 repress from Progress 353 CpΠK (terminate)
14:55-17:25		Progress 353 transfer and IMS ops
15:35-16:20	FE-1	Setting up PCS at RWS (A31P) in cupola
16:20-17:05		PCS HDD Cloning
17:05-17:20		Stowing one A31P and retrieving another
17:20-18:05		PCS HDD Cloning
17:25-17:45	CDR	IMS file prep
17:45-18:15		СОЖ maintenance. Check ИП-1 position
18:05-18:15	FE-1	CWC inventory audit
18:15-18:45	CDR	Daily plan review
18:15-18:40	=FE-1	Daily plan review
18:40-18:45		Disconnect DCP power cable
18:45-19:00		Daily planning conference (S-band)
19:00-19:30		Report prep
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	CDR	Urine transfer from ЕДВ-У to Progress 353 Rodnik Water Tanks [БВ] 1 and 2
		RSE1 laptop checkout

Note: See OSTP for references to US activities.

End of Radiogram