Radiogram No. 9737u Form 24 for 02/01/05 Plasma Crystal-3". [OBC] 2 Test

Plasma Crysta GMT	CREW	ACTIVITY
06:00-06:10	CDR	Morning inspection
06:00-06:10	FE-1	Morning inspection. Inspection of CB on switch panel (БВП) and fuses on fuse box panel БПП-30, БПП-36 in DC1
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Prep for work
08:00-08:15		Daily planning conference (S-band)
08:15-09:15	CDR	EarthKAM: set up, activation
08:15-09:15	FE-1	PLASMA CRYSTAL-3. 35 chamber and line evacuation. <i>Tagup with specialists.</i> (S-band)
09:15-10:05		Kazbek fit check
10:05-11:35	CDR	Physical Exercise (RED)
10:05-11:35	FE-1	Physical Exercise (TVIS) day 2
11:35-12:35	CDR	Physical Exercise (TVIS)
11:35-11:50		Motorola phone charge - setup. Tagup w/specialists as needed. (S-band)
12:05-12:10	FE-1	Motorola phone charge: charge monitoring.
12:15-12:20		PLASMA CRYSTAL-3. Post-Evacuation Leak Check
12:25-12:30		Motorola phone charge: charge monitoring
12:35-12:40	CDR	TVIS/RED/HRM data transfer to MEC
12:40-12:50		Airlock Fire Port Labeling
12:45-12:50	FE-1	Motorola phone charge: charge monitoring
12:50-13:00	=	Motorola phone charge: Tear Down
12:50-12:55	CDR	TEPC data calldown
13:00-13:30		Tagup on equipment pre-pack for return on Shuttle (S-band)
13:30-14:30		LUNCH
14:30-15:20	FE-1	Equipment pre-pack for return on Shuttle
14:30-16:45	CDR	Equipment pre-pack for return on oriatile
15:20-15:25		PLASMA CRYSTAL-3. Post-Evacuation Leak Check
15:25-16:15	FE-1	Equipment pre-pack for return on Shuttle
16:15-16:55		PLASMA CRYSTAL-3. Software load. Tagup w/specialists (S-band)
16:45-16:55	CDR	PAO set up and prep.
16:55-17:05		PAO crew prep
17:05-17:25		Video downlink dedicated to 2-nd Anniversary of Columbia Accident (Ku+S-band)
17:25-18:25	FE-1	Physical Exercise (VELO + Force Loader/cycle 1) day 2
17:30-18:00		СОЖ maintenance
18:00-18:20	CDR	IMS file prep
18:20-18:40		Daily plan review
18:25-18:35	FE-1	Bally plant review
18:35-18:40	FE-1	PLASMA CRYSTAL-3. Post-Evacuation Leak Check
18:40-18:55		Daily planning conference (S-band)
18:55-19:10	CDR	Private conference per crew's request (Ku+S-band)
18:55-19:15	FE-1	Report prep
19:15-19:30	FE-1	Private medical conference (S-band)

19:10-19:15	CDR	Report prep
19:15-19:45	CDR	Daily food prep
19:30-19:45	FE-1	
19:45-20:15		DINNER
20:15-21:15	CDR	Pre-sleep
20:15-21:20	FE-1	
21:15-21:30	CDR	Private medical conference (S-band)
21:20-21:25	FE-1	PLASMA CRYSTAL-3. Post-Evacuation Leak Check
21:25-21:30		PLASMA CRYSTAL-3. Turbo pump deactivation
21:30-06:00		SLEEP

Note: See OSTP for references to US activities

End of radiogram