PLASMA CRYSTALL EXPERIMENT

GMT	CREW	ACTIVITY
06:00-06:05	FE-1	ПК-3 PLUS. Turbo-pump activation
06:00-06:10	CDR FE-1	Morning inspection
06:05-06:10		
06:10-06:40		Post-sleep
06:40-07:30	-	BREAKFAST
07:30-07:45	FE-1	Work prep
07:45-08:00		Daily planning conference (S-band)
08:00-08:15	FE-1	Work prep
08:00-08:10		
08:10-08:15		CSA-O2 Status Check
08:15-09:05	CDR	Replacing filters in Dust Collectors $\Pi\Phi1$, $\Pi\Phi2$ ($\Phi\GammaB1\Pi\Gamma0_2_226_1$ in bag # 352-2, update IMS to reflect replacement, discard removed filters) and cleaning fan screens B1, B2 in DC1.
08:15-08:45		PLANTS-2. Photo- and video imagery
09:00-09:50	FE-1	TV (ISS-MCC) ПК-3 PLUS Experiment ops (start). Tagup with specialists (S-band + VHF)
09:05-10:05	CDR	Cleaning Fan B3 screen in DC1
09:50-11:00	FE-1	IFM СД1-5M, СД1-6 in АСУ (toilet)
10:05-10:25	CDR	IMS conference (S-band)
10:25-11:10	CDIC	TVIS Monthly Maintenance
11:00-11:15	FE-1	ПК-3 PLUS. Experiment ops (termination). Tagup with specialists (VHF)
11:10-12:10	CDR	Physical exercise (TVIS)
11:15-11:55	FE-1	ПК-3 PLUS. Copy data from the hard drive. <i>Tagup with specialists (S-band)</i>
11:55-12:25	. – '	ПК-3 PLUS. Hardware deactivation. <i>Tagup with specialists (S-band)</i>
12:10-12:20	CDR	TVIS Weekly Maintenance
12:20-13:50	OBIX	Physical Exercise (RED)
12:25-13:55	FE-1	Physical Exercise (TVIS) Day 3
13:50-13:55	CDR	BCAT-3: camera checkout
13:55-14:55		LUNCH
14:55-16:15	CDR	A/L restow post ROOBA installation
14:55-15:55	FE-1	ПК-3 PLUS. Hardware stow. <i>Tagup with specialists (S-band)</i>
15:55-16:45	ļ. – .	Pille dosimeter reading
16:15-16:45	CDR	СОЖ maintenance
16:45-17:15		Expedition 12 and 13 crew conference (S-band)
17:15-18:15	FE-1	Physical Exercise (VELO + RED) day 3
17:15-17:35		Start BSA battery charge
17:35-17:55	CDR	Start EMU battery charge
17:55-18:15		IMS update
18:15-18:20		Transferring TVIS, RED, and HRM data to MEC
18:20-18:50		Daily plan review
18:50-19:05		Daily planning conference (S-band)

19:05-19:30		Report prep
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	FE-1	ODF replacement
		GCF-JAXA. ТБУ incubator temperature check
		BIO-5. PLANTS-2. Payload status check

Note: See OSTP for references to US activities. End of Radiogram