Radiogram No. 9729u Form 24 for 01.31.05 Emergency Descent OBT. Plasma Crystal.

06:10-06:40 Post-sleep 06:40-06:50 FE-1 MO-8. System set up 06:40-06:50 CDR Body mass measurement 06:50-07:05 CDR Body mass measurement 06:50-07:05 FE-1 Calf measurement 07:05-07:55 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:10 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 11:20-14:20 LUNCH 14:20-14:20 LUNCH 14:20-14:20 LUNCH 15:10-15:15 FE-1 ELECTRON activation. Tagup (S-band) 15:20-16:20 FE-1 <	Emergency Descent OBT. Plasma Crystal.			
06:10-06:40 Post-sleep 06:40-06:50 FE-1 MO-8. System set up 06:40-06:50 CDR Body mass measurement 06:50-07:05 CDR Body mass measurement 06:50-07:05 FE-1 Calf measurement 07:05-07:55 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:10 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 11:20-14:20 LUNCH 14:20-14:20 LUNCH 14:20-14:20 LUNCH 15:10-15:15 FE-1 ELECTRON activation. Tagup (S-band) 15:20-16:20 FE-1 <	GMT	Crew	Activity	
06:40-06:50 FE-1 MO-8. System set up 06:40-06:50 CDR Calf measurement 06:50-07:05 CDR Body mass measurement 06:50-07:05 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 BOHAKFAST 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-13:10 GDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-14:20 LUNCH 14:20-14:40 FE-1 ELECTRON activation Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1	06:00-06:10		Morning inspection	
06:40-06:50 CDR Calf measurement 06:50-07:05 CDR Body mass measurement 06:50-07:05 FE-1 Calf measurement 07:05-07:55 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-16:20 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation. Tagup (S-band) 16:20-16:40	06:10-06:40		Post-sleep	
06:50-07:05 CDR Body mass measurement 06:50-07:00 FE-1 Calf measurement 07:05-07:55 CDR BREAKFAST 07:05-07:30 FE-1 Body mass measurement 07:20-07:30 FE-1 BOR-AKFAST 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:40-11:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-13:10 FE-1 Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45	06:40-06:50	FE-1	MO-8. System set up	
06:50-07:00 FE-1 Calf measurement 07:05-07:25 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:45-08:25 FE-1 Prep for work 08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-13:10 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-16:20 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation with to 32A). Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physi	06:40-06:50	CDR	Calf measurement	
07:05-07:55 CDR BREAKFAST 07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:50-82:5 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1	06:50-07:05	CDR	Body mass measurement	
07:05-07:20 FE-1 Body mass measurement 07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 DPC (S-band) 08:40-11:40 Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation. Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Pos	06:50-07:00	FE-1	Calf measurement	
07:20-07:30 FE-1 MO-8. Closeout ops 07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS)	07:05-07:55	CDR	BREAKFAST	
07:30-08:15 FE-1 BREAKFAST 07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-14:20 . LUNCH 14:20-14:20 . LUNCH 14:20-14:20 . LUNCH 14:20-14:20 . LUNCH 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 16:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) <t< td=""><td>07:05-07:20</td><td>FE-1</td><td>Body mass measurement</td></t<>	07:05-07:20	FE-1	Body mass measurement	
07:55-08:25 CDR Prep for work 08:15-08:25 FE-1 Prep for work 08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠχΟ to initial. Report to MCC-M each item on hardware placement in Γχο.	07:20-07:30	FE-1	MO-8. Closeout ops	
08:15-08:25 FE-1 Prep for work 08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠΧΟ to initial. Report to MCC-M each item on hardware placement in ΠΧΟ. 17:45-17:50 CDR TVIS weekly maintenance <t< td=""><td>07:30-08:15</td><td>FE-1</td><td>BREAKFAST</td></t<>	07:30-08:15	FE-1	BREAKFAST	
08:25-08:40 . DPC (S-band) 08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA TiXO to initial. Report to MCC-M each item on hardware placement in TiXO. 17:45-17:50	07:55-08:25	CDR	Prep for work	
08:40-11:40 . Emergency descent OBT. Tagup (S-band) 11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 . LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30	08:15-08:25	FE-1	Prep for work	
11:40-13:10 FE-1 Physical Exercise (TVIS) day 1 11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:30-19:00 Daily plan review 19:00-19:30	08:25-08:40		DPC (S-band)	
11:40-11:50 CDR RED: routine inspection 11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR IMS file prep 18:30-19:00 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . <td< td=""><td>08:40-11:40</td><td></td><td>Emergency descent OBT. Tagup (S-band)</td></td<>	08:40-11:40		Emergency descent OBT. Tagup (S-band)	
11:50-13:20 CDR Physical Exercise (RED) 13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠλΟ to initial. Report to MCC-M each item on hardware placement in ΠλΟ. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 </td <td>11:40-13:10</td> <td>FE-1</td> <td>Physical Exercise (TVIS) day 1</td>	11:40-13:10	FE-1	Physical Exercise (TVIS) day 1	
13:20-14:20 LUNCH 14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	11:40-11:50	CDR	RED: routine inspection	
14:20-16:20 CDR Installation of new SSC A31P laptops in RS 14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	11:50-13:20	CDR	Physical Exercise (RED)	
14:20-14:40 FE-1 ELECTRON activation. Tagup (S-band) 15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	13:20-14:20		LUNCH	
15:10-15:15 FE-1 ELECTRON activation (switch to 32A). Tagup (S-band) 15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	14:20-16:20	CDR	Installation of new SSC A31P laptops in RS	
15:20-16:20 FE-1 PLASMA CRYSTAL-3. Hardware set up. Tagup (S-band) 16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:55-18:15 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	14:20-14:40	FE-1	ELECTRON activation. Tagup (S-band)	
16:20-16:40 FE-1 PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band) 16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	15:10-15:15	FE-1	ELECTRON activation (switch to 32A). Tagup (S-band)	
16:25-16:45 CDR TEPC transfer 16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	15:20-16:20	FE-1	PLASMA CRYSTAL-3. Hardware set up. <i>Tagup (S-band)</i>	
16:40-17:40 FE-1 Physical Exercise (VELO+HC-1) day 1 16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	16:20-16:40	FE-1	PLASMA CRYSTAL-3. Leak check before vacuuming. Tagup (S-band)	
16:45-17:45 CDR Physical Exercise (TVIS) 17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	16:25-16:45	CDR	TEPC transfer	
17:40-18:15 FE-1 Post-EVA ΠxO to initial. Report to MCC-M each item on hardware placement in ΠxO. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 DPC (S-band) 18:30-19:00 Daily plan review 19:00-19:30 Report prep 19:30-20:00 Daily food prep 20:00-20:30 DINNER	16:40-17:40	FE-1	Physical Exercise (VELO+HC-1) day 1	
17:40-10:13 FE-1 ПхО. 17:45-17:50 CDR TVIS weekly maintenance 17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	16:45-17:45	CDR	Physical Exercise (TVIS)	
17:50-17:55 CDR TVIS/RED/HRM date transfer to MEC 17:55-18:15 CDR IMS file prep 18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	17:40-18:15	FE-1		
17:55-18:15 CDR IMS file prep 18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	17:45-17:50	CDR	TVIS weekly maintenance	
18:15-18:30 . DPC (S-band) 18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	17:50-17:55	CDR	TVIS/RED/HRM date transfer to MEC	
18:30-19:00 . Daily plan review 19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	17:55-18:15	CDR	IMS file prep	
19:00-19:30 . Report prep 19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	18:15-18:30		DPC (S-band)	
19:30-20:00 . Daily food prep 20:00-20:30 . DINNER	18:30-19:00		Daily plan review	
20:00-20:30 . DINNER	19:00-19:30		Report prep	
	19:30-20:00		Daily food prep	
20:30-21:30 Pre-sleep	20:00-20:30		DINNER	
	20:30-21:30		Pre-sleep	
21:30-06:00 . SLEEP	21:30-06:00		SLEEP	
Task List FE-1 PLANTS-2. Hardware monitoring	Task List	FE-1	PLANTS-2. Hardware monitoring	

Note: See OSTP for references to USOS activities

End of radiogram