Radiogram No. 7314u Form 24 for 03/24-25/08 Shuttle Undocking from PMA2. Plasma Crystal-3

	Plasma Crystal-3
	ACTIVITY
FE-2-16	Integrate Immune - FE-2 1J/A Liquid Saliva Sample Collection
FE-1	PLASMA CRYSTAL-3 PLUS. Turbo-pump activation
CDR, FE-2	
FE-1	Morning Inspection
FE-2-16	
FE-2, FE-1, CDR	Post-sleep
FE-2-16	
CDR, FE-1, FE-2	BREAKFAST
FE-2-16	
FE-1, CDR, FE-2	Prep for Work
FE-2-16	Prep for Work
FE-1	Transfer urine from EDV-U to Progress 363 Rodnik Water Tank 1 [6B1]
CDR	Deactivation of orbital accelerometer RSU in NODE2
EE 2 16	Integrate Immune - FE-2 1J/A Saliva Sample Hardware Stow
FE-2-10	IWIS deactivation
CDR, FE-2	Double Cold Bag Packing Familiarization
FE-2	Double Cold Bag (DCB) Packing
CDB	CDRA LTL Disconnect
CDK	Double Cold Bag (DCB) Packing
FE-2-16	Integrate Immune - FE-2 1J/A Saliva Sample Hardware Setup
FE-1	ISS-MCC TV. PLASMA CRYSTAL-3 PLUS. Experiment (start)
FE-2-16	Integrate Immune - FE-2 1J/A Blood Sample Collection
CDR	CEVIS monthly maintenance
FE-2-16	Integrate Immune - Blood Sample Hardware Stow for CDR
FE-2	DCB transfer
FE-2-16	VTR bypass cable reconfig
FE-1	PLASMA CRYSTAL. Manual experiment ops
FE-2, FE-2-16	Handover
CDR	BPSMU stow
FE-1	PLASMA CRYSTAL-3 PLUS. Experiment (termination)
	ISS and Shuttle crew farewell
FE-1	PLASMA CRYSTAL-3 PLUS. Copy and downlink data from the hard drive
CDR	ISS-Shuttle hatch closure
FE-2-16	Physical Exercise (TVIS)
CDR	Physical Exercise (CEVIS)
FE-1	PLASMA CRYSTAL-3 PLUS. Hardware teardown
	СОЖ Maintenance
FE-2-16	Elite-S2 – cable stowage
CDR	PMA2 config prior to Shuttle departure
	CREW FE-2-16 FE-1 CDR, FE-2 FE-1 FE-2-16 FE-2, FE-1, CDR FE-2-16 CDR, FE-1, FE-2 FE-2-16 FE-1, CDR, FE-2 FE-2-16 CDR, FE-2 FE-2-16 CDR FE-2-16 CDR FE-2-16 FE-1 FE-2-16 CDR FE-2-16 FE-1 FE-2-16 CDR FE-1 FE-2-16 CDR FE-2-16 FE-1 FE-2-16 FE-1 FE-2-16 CDR FE-1 FE-1 FE-1 FE-1 FE-1 CDR FE-1

23:15-23:20	FE-2-16	Transfer and connect EXPRESS Laptop Video Cable and A31p Video Adapter from EXPRESS Rack 5 to EXPRESS Rack 2
23:20-23:55	FE-1	PMA2 config for Shuttle departure
23:45-00:50	CDR	PMA2 depress
23:45-00:05	FE-2-16	PHOTO/TV – Prep of Return Documentation
00:20-01:20	FE-1	Physical Exercise (VELO+RED), day 2
00:40-01:25	FE-2-16	ELITE - ER2 Rack Setup
00:50-01:10	CDR	PMA2 leak check
01:10-01:15		Japanese Experiment Logistics Module-Pressurized Section (JLP) Minimum Keep Active Monitor (MKAM) fan activation
01:15-01:20		Portable Breathing Apparatus (PBA) Transfer from JLP to NODE1
01:20-01:35	FE-1	Verify ИП-1 Flow Meter Positions
01:20-01:25		Japanese Experiment Logistics Module-Pressurized Section (JLP) Minimum Keep Active Monitor (MKAM) Fan Deactivation
01:25-01:30	CDR	J01 VCP cap removal and stowage on S3 v/port in N2
01:30-01:35		Transfer TVIS/RED/CEVIS/HRM data to MEC
01:40-02:00		PMA2 leak check
01:40-01:45	FE-1	Restore nominal comm config
01:50-01:55	FE-2-16	Disconnect Display and Control Panel (DCP) power cable
02:00-02:30		DINNER
02:30-02:50	CDR	PMA2 leak check
02:30-03:00	FE-1, FE-2-16	Pre-sleep
02:50-03:00	CDR	
03:00-11:30		SLEEP
Task List	FE-1	ТБУ (Universal Bioengineering Thermostat). Temperature check
		PLANTS-2. Payload Status Check and Photography
		IMS update

Notes:

- See OSTP for references to US activities.
 SM Window #9 shutter opening is at crew discretion w/ Report to MCC
 There is a tag up scheduled with specialists during all PLASMA CRYSTAL 3 PLUS activities (S-band
- + VHF)

End of Radiogram