TRANSFERRING RAW ACH DATA TO A FLASH CARD

| GMT | CREW | ACTIVITY |
|-------------|-----------|--|
| 06:00-06:10 | | Morning Inspection |
| 06:10-06:40 | | Post-sleep |
| 06:40-07:30 | | BREAKFAST |
| 09:00-10:00 | CDR | Transferring raw ACH data to a flash-card and OCA downlink. <i>Tagup with specialists (S-band)</i> |
| 10:40-12:10 | FE-1 | Physical Exercise (TVIS), day 4 |
| 11:00-12:00 | FE-2 | Physical Exercise (RED) |
| 12:00-13:00 | CDR | Physical Exercise (VELO+RED), day 4 |
| 13:00-14:00 | | LUNCH |
| 14:00-14:40 | FE-1 | СОЖ maintenance |
| 15:00-16:30 | FE-2 | Physical Exercise (TVIS) |
| 16:15-17:15 | FE-1 | Physical Exercise (VELO + RED), day 4 |
| 16:45-18:15 | CDR | Physical Exercise (TVIS), day 4 |
| 18:15-18:45 | | Evening work prep |
| 18:45-19:00 | | Daily Planning Conference (S-band) |
| 19:00-19:30 | | Evening work prep |
| 19:30-20:00 | | DINNER |
| 20:00-20:30 | CDR, FE-1 | Daily Food Prep |
| 20:00-20:07 | FE-2 | Daily Food Prep |
| 20:07-20:22 | FE-2 | Private Family Conference (Ku + S-band) |
| 20:22-20:30 | FE-2 | Daily Food Prep |
| 20:30-21:30 | | Pre-sleep |
| 21:30-06:00 | | SLEEP |
| Task List | CDR | URAGAN. Observation and photography |
| | FE-1 | GCF-JAXA. ТБУ temperature monitoring (in the morning) |
| | | PLANTS-1. Payload status check (in the morning) |
| | | DIATOMEA. World Ocean Observations |

Note: See OSTP for references to US activities.

End of Radiogram