Radiogram No. 9935u Form 24 for 08/09/2012 SM Kurs-P Test in a Loop (on DC1 -Y side) with TFK 416

GMT	CREW	ACTIVITY
06:00-06:15	CDR	SPRUT-2. Config Setup, Body Mass Measurement Tagup (Sband)
06:00-06:05	FE-5	Urine Spot Test
06:00-06:10	FE-2	SONOCARD Experiment Termination /
06:00-06:10	FE-3, FE-6	Morning Inspection
06:00-06:10	FE-4	Morning Inspection SM TICC [Caution & Warning Panel] Test
06:05-06:10	FE-5	Morning Inspection
06:10-06:15	FE-2	Post-sleep
06:10-06:30	FE-4	Post-sleep
06:10-06:40	FE-3, FE-5, FE- 6	Post-sleep
06:15-07:00	CDR	SPRUT-2. Experiment Ops. Tagup (S-band)r/g 9954
06:15-06:30	FE-2	SPRUT-2. Body Mass Measurement and Closeout Ops. Tagup (Sband)
06:30-06:40	FE-4	SPRUT-2. Photography
06:30-07:00	FE-2	Post-sleep
06:40-07:30	FE-3, FE-4 , FE-5, FE-6	BREAKFAST
07:00-07:50	FE-2	SPRUT-2. Experiment Ops. Tagup (S-band)
07:00-07:20	CDR	Post-sleep
07:20-08:00	CDR	BREAKFAST
07:30-07:40	FE-3	Work Prep
07:30-07:50	FE-6	Work Prep
07:30-08:00	FE-4	Work Prep
07:30-07:50	FE-5	Work Prep
07:40-07:50	FE-3	CIR Alignment Guide Installation
07:50-08:00	FE-2	BREAKFAST
07:50-08:00	FE-3	P/TV - SSC Activation
07:50-08:00	FE-5	Glove Box (MSG) Activation
07:50-08:00	FE-6	Activation of JEMRMS RLT Laptop
08:05-08:25		Daily Planning Conference (S-band)
08:25-08:40	FE-2	SONOCARD Copy Data to RSE-MED Laptop
08:25-08:40	FE-5	YTSL - Photography
08:25-08:35	FE-6	JEMRMS Final Activation Part 1
08:25-08:30	CDR	Work Prep
08:25-08:35	FE-4	Work Prep
08:35-10:40	CDR, FE-4	DC1 and ΠxO preparation for EVA
08:30-08:45	FE-3	JEMRMS - DOUG Start
08:35-08:45	FE-6	JEMRMS - Start Monitoring
08:40-09:20	FE-2	BREAKFAST
08:40-08:50	FE-5	BLR48. Preparation for the second part of 48-hour monitoring.
08:45-09:25	FE-3, FE-6	JEMRMS MCE Unberth
08:55-09:15	FE-5	HMS Visual Testing Activity

09:15-10:15	FE-5	BASS. Burn Ops Start
09:20-10:20	FE-2	Cleaning ventilation screens on FGB interior panels (panels 201, 301, 401)
09:25-10:30	FE-3, FE-6	JEMRMS MCE Installation
10:15-11:45	FE-5	Physical Exercise (ARED)
10:15-11:45	FE-2	FGB Dust Collector ΠC1, ΠC2 Filter Replacement (ΦΓ51ΠΓΟ_2_219_1, bag 410-32 (b/c 00054260R)) Discard the removed items. Update the IMS
10:30-10:50	FE-3, FE-6	JEMRMS MCE Berthing
10:40-11:15	FE-4	Photo of A31-A1 Hose in CPBK-2M
10:40-11:20	CDR	СОЖ Maintenance /
10:50-11:00	FE-6	JEMRMS Mode Transition to MA Brake
10:50-11:00	FE-3	JEMRMS Monitor Stop
11:00-11:10	FE-6	JEMRMS USB Check
11:10-11:25	FE-6	JEMRMS Data Transfer
11:10-11:20	FE-2	PAO Hardware Setup
11:20-11:30	CDR, FE-2, FE-4	Crew Prep for PAO/
11:25-11:35	FE-6	JEMRMS Deactivation Preparation
11:30-11:50	CDR, FE-2, FE-4	TV Greetings (S + Ku - band)
11:45-11:55	FE-5	BLR48. Second Half of 48 hours Holter Measurements
11:50-12:10	FE-6	HMS Visual Testing Activity
11:50-13:20	FE-2	Physical Exercise (ARED)
11:50-13:20	CDR	Physical Exercise (TVIS), Day 1
11:55-12:45	FE-5	ICV Monitoring Prep
12:20-12:40	FE-3	HMS Visual Testing Activity
12:20-13:20	FE-4	Physical Exercise (VELO), Day 1
12:40-12:55	FE-3	Journal Entry
12:40-12:50	FE-6	PAO Hardware Setup
12:45-13:00	FE-5	BLR48. Holter and Actiwatch Data Exchange and Synch
12:50-13:00	FE-6	Crew Prep for PAO
12:55-13:05	FE-3	CWC Audit
13:00-13:20	FE-6	PAO Event
13:15-13:20	FE-3	Space Headaches Questionnaire
13:20-14:20		LUNCH
14:20-15:40	FE-2	Cleaning Ventilation Screens on FGB Interior Panels (panels 116, 316, 231, 431)
14:20-14:25	FE-5	PROK Diet Logging (Day 1)
14:25-14:55	FE-3, FE-5	DOUG Software Review
14:40-15:35	CDR, FE-4	DC1 and ΠxO preparation for EVA
14:40-14:50	FE-6	SSC Application Deactivation
14:55-15:55	FE-3	Node 1, Node 2 and Node 3 Bacteria Filter Cleaning
14:55-15:10	FE-5	Journal Entry
15:25-16:25	FE-5	Physical Exercise (T2)
15:40-17:10	FE-2	FGB ΓЖТ-4 BT-7 Fan Screen Cleaning

15:55-16:55	FE-3	Physical Exercise (CEVIS)
16:25-17:10	FE-4 , FE-5, FE-6	CHeCS Medical Emergency Training
16:55-18:25	FE-3	Physical Exercise (ARED)
17:10-17:40	CDR, FE-4 (assists)	Hand Ergometry Test To=17:11 . Tagup (VHF)
17:10-18:10	FE-2	Physical Exercise (TVIS), Day 4
17:10-18:40	FE-5	BASS. Burn Closeout Ops
17:10-17:55	FE-6	ALTEA. Shield Tile Reconfiguration
17:55-18:05	FE-6	Photography of Sensor Installation in Columbus
18:05-18:35	FE-6	Evening Work Prep
18:10-18:40	CDR, FE-4	Evening Work Prep
18:25-18:40	FE-3	IMS and Stowage Conference
18:30-19:10	FE-2	Evening Work Prep
18:35-18:40	FE-6	ISS HAM Radio Setup in Service Module
18:40-19:00	FE-3,FE-5	Evening Work Prep
18:40-19:10	FE-4, CDR (assists)	Hand Ergometry Test <i>To=18:44</i> . <i>Tagup (VHF)</i>
18:40-18:55	FE-6	ISS HAM Radio Session from SM
18:55-19:10	FE-6	Evening Work Prep
19:00-19:10	FE-5	Glove Box (MSG) Powerdown
19:10-19:35		Daily Planning Conference (S-band)
19:35-21:30	FE-2, FE-4 , FE-5, FE-6	Pre-sleep
19:35-21:20	CDR	Pre-sleep
19:35-19:40	FE-3	P/TV Playback Start
19:40-21:25	FE-3	Pre-sleep
21:20-21:30	CDR	SONOCARD Experiment Start
21:25-21:30	FE-3	P/TV Playback Stop
21:30-06:00		SLEEP
TASK LIST	FE-2	IMS Update /
	CDR, FE-4	ECON. Observations and Photography
	CDR, FE-2, FE- 4	Preparation of reports for Roskosmos site

Notes:

- 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC

- See OSTP for references to US activities
 Pre-sleep ops: daily food prep, dinner, pre-sleep
 No T2 Exercise at 08:45-10:50 No VELO Exercise at 14:00-16:30