## Stowing hardware for disposal in Progress. ВД-СУ Mode Deactivation/Activation and БИТС Power Off/On.

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Work prep
08:00-08:15		Daily planning conference (S-band)
08:15-11:05	CDR	Stow disposal items in Progress №352 (with IMS support)
08:15-09:45	FE-1	US equipment prep for disposal in Progress
09:45-11:15	FE-1	Stow disposal items in Progress №352 (with IMS support)
11:05-11:15	CDR	<b>Report to MCC</b> when equipment stowage for disposal in Progress 352 is completed (S-band)
11:15-11:45	FE-1	Defibrillator checkout
11:15-11:50	CDR	SFOG Candle Replacement and Activation <i>Report to MCC</i> part numbers of used candles
11:50-13:20	CDR	Physical exercise (TVIS), day 1
11:50-13:20	FE-1	Physical Exercise (RED)
13:20-14:20		LUNCH
14:20-14:30	CDR	On MCC Go Demate УС-21 telemetry data connector from БИТС2-12
14:30-15:20	CDR	Removing YC-21 box from Progress 352
14:45-15:20	FE-1	SFOG Candle Replacement and Activation. <i>Report to MCC</i> part numbers of used candles
15:20-16:20		Install Progress 352 docking mechanism
16:20-16:50	CDR	Urine receptacle and filter-insert replacement in ACY. (Use urine receptacle #1030131 b/c 009261R, ΦΓБ1ΠΓΟ_3_304_1 and filter insert #301032, CM1PO_1_135_1, white bag #350-8. Discard removed items. Update the IMS.)
16:20-17:20	FE-1	Physical Exercise (TVIS)
17:15-18:15	CDR	Physical Exercise (VELO+Load Trainer/cycle 1) day 1
17:20-17:40	FE-1	IMS file prep
17:40-18:10	FE-1	СОЖ maintenance
18:10-18:15	FE-1	Transfer TVIS, RED, and HRM data to MEC
18:15-18:45		Daily plan review
18:45-19:15		Report prep
19:15-19:30		Daily planning conference (S-band)
19:30-20:00		DINNER
20:00-20:30		Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	CDR	URAGAN Observation and photo imagery
		PLANTS-2. Payload status check

Note: See OSTP for references to US activities.

End of radiogram