Radiogram No. 9740u Form 24 for 02/02/05 SM Propulsion System (ОДУ) Leak Check. Plasma Crystal

GMT	CREW	ACTIVITY
06:00-06:05	FE -1	PLASMA CRYSTAL-3. Turbo pump activation
06:00-06:10	CDR	
06:05-06:15	FE -1	Morning inspection
06:10-06:40	CDR	
06:15-06:45	FE -1	Post-sleep
06:40-07:30	CDR	
06:45-07:35	FE -1	BREAKFAST
07:30-08:00	CDR FE -1	Prep for work
07:35-08:00		
08:00-08:15	L -	Daily planning conference (S-band)
08:15-10:15	CDR	Food rations audit
08:15-10:15	CDK	
	4	System set up for Rodnik water tank 1 shell compression in Progress 351 ТЛФ3 Regul-Packet channel check
08:45-08:55	FE -1	Ü
08:55-09:35	F	PLASMA CRYSTAL-3. Set up Tagup with specialists (S-band)
09:35-10:10		ISS-MCC TV. PLASMA CRYSTAL-3 ops (start). Tagup with specialists (VHF)
10:10-11:40		Rodnik water tank 1 shell compression in Progress 351
10:15-11:45	CDR	Physical Exercise (RED)
11:40-11:50	FE -1	Rodnik water tank 1 shell compression in Progress 351, switching to another water tank
11:45-12:45	CDR	Physical Exercise (CEVIS)
11:50-12:00		PLASMA CRYSTAL-3. Experiment (end)
12:00-12:10	FE -1	ТЛФ3 Regul-Packet channel check
12:10-13:40		Physical Exercise (TVIS) day 3
12:45-12:50		TVIS/RED/HRM data transfer to MEC
12:50-12:55		HAM radio set up
12:55-13:05	CDR	HAM radio pass
13:05-13:10		TEPC display data calldown
13:10-13:40		Prepack items for return on Shuttle flight
13:40-14:40		LUNCH
14:40-17:20	CDR	Prepack items for return on Shuttle flight
14:40-16:25	FE -1	Rodnik water tank 2 shell compression in Progress 351
16:25-17:25		Physical Exercise (VELO + Force Loader/cycle 1) day 3
17:20-17:35	CDR	SEM: video equipment set up
17:35-17:50		SEM video history
17:50-18:20	FE -1	СОЖ maintenance. Check set up of ИП-1 sensors
17:50-18:10		Prepack items for return on Shuttle flight
18:10-18:30	CDR	IMS file prep
18:20-18:40	FE -1	Daily plan review
18:30-18:40	CDR	
18:40-18:55		Daily planning conference (S-band)
18:55-19:05	CDR	Daily plan review
18:55-19:25	FE -1	Report prep
19:05-19:30	CDR	
13.00 13.00	JULIA	

19:25-20:00	FE -1	Daily food prep
19:30-20:00	CDR	
20:00-20:30		DINNER
20:30-21:30	CDR	Pre-sleep
20:30-21:25	FE -1	
21:25-21:30	FE -1	PLASMA CRYSTAL-3. Turbo pump deactivation
21:30-06:00		SLEEP
Task List	FE -1	PLANTS-2. Hardware monitoring

Note: See OSTP for references to US activities End of radiogram