r/g 8613u form 24 for 09.24/08 In-Flight Maintenance for monoblock TA968 MA (ПЦБ) FETC2-12.

GMT	CREW	ACTIVITY
06:00- 06:10	CDR, FE-2	Morning Inspection
06:00- 06:10	FE-1	SONOCARD. Experiment completion
06:10- 06:40	CDR,FE-2	Post-sleep
06:10- 06:20	FE-1	Morning Inspection
06:20- 06:40	FE-1	Post-sleep
06:40- 07:30		Breakfast
07:30- 07:45		Daily planning conference (S-band)
07:45- 08:15	FE-2	Work prep
07:45- 08:00	CDR,FE-1	Work prep
08:00- 08:15	FE-1	Sonocard. Copy data to Laptop RSE-MED
08:00- 09:00	CDR	In-Flight Maintenance for monoblock TA968MA (ПЦБ) from FETC2-12 system - preparation . <i>Conference with specialists (S-band)</i>
08:15- 10:45	FE-1	FGB Structure and HW surface sampling. Conf. with specialists if needed. (S-band)
08:15- 09:45	FE-2	FE (RED)
09:00- 12:00	CDR	On MCC-M Go In-Flight Maintenance for monoblock TA968MA (ПЦБ) from FETC2-12 system. Conf. with specialists. (S-band)
09:45- 10:45	FE-2	FE (CEVIS)
10:45- 11:40	FE-1	Cleaning of detachable grilles of Gas-Liquid Heat Exchangers 1, 2, 3 FGB
10:45- 11:00	FE-2	Locating hard drives with software R11 for PCS
11:00- 11:30	FE-2	Replacing hard drives for PCS
11:30- 12:45	FE-2	In-Flight Maintenance - RED
11:40- 13:10	FE-1	FE (TVIS) -3
12:00- 13:00	CDR	On MCC-M Go In-Flight Maintenance for monoblock TA968MA (ПЦБ) from FETC2-12 system. Last steps. Conf. with specialists. (S-band)
12:45- 13:30	FE-2	In-Flight RED calibration.
13:00- 14:00	CDR	FE (TVIS) -3
13:10- 13:20	FE-1	Rastenia-2. Data copying (start) / r/g
13:20- 13:40	FE-1	On MCC-M Go Electron deactivation with purge
13:40- 13:50	FE-1	On MCC-M Go Checking connectivity for new Ethernet network clients r/g

14:00- 15:00		Midday Meal
15:00- 18:30	FE-2	Unpacking and stowing new US h/w from Progress 365
15:00- 15:30	FE-1	RASTENIA-2. Sample collection and equipment safing. Conf with specialists. (S-band) / r/g
15:00- 16:20	CDR	Transferring contents from ЕДВ-У to WT1 of Progress 365
15:30- 15:40	FE-1	MELFI – sample installation
15:40- 15:55	FE-1	Matryoshka-P. Replacing and checking performace of PCMCIA card in ACT spectrometer
15:55- 16:10	FE-1	ИП-1 sensors installation check, installing ИП-1 sensors on ПрК-СУ hatch
16:10- 16:40	FE-1	Measuring trace contaminants in SM using CMS
16:30- 18:00	CDR	FE (TVIS) -3
16:40- 17:00	FE-1	IMS update
17:45- 18:45	FE-1	FE (TVIS) -3
18:10- 19:10	CDR	Work prep
18:30- 19:15	FE-2	Work prep
18:45- 19:15	FE-1	Work prep
19:10- 19:15	CDR	TVIS, RED and HRM data transfer to MEC
19:15- 19:30		Pre-sleep
19:30- 19:45		Daily planning conference (S-band)
19:45- 20:15		Evening Meal
20:15- 20:45		Daily food prep
20:45- 21:25	FE-2	Pre-sleep
20:45- 21:20	CDR	Pre-sleep
20:45- 21:30	FE-1	Pre-sleep
21:20- 21:30	CDR	SONOCARD. Experiment start
21:25- 21:30	FE-2	Questionnaire – log entries
21:30- 06:00		Sleep
Task List	CDR	СОЖ Maintenance