Radiogram No. 759nu (UPDATED) ATV Control Panel Set up

Form 24 for 06/27/05

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Work prep
07:45-08:00		Daily planning conference (S-band)
08:00-08:15		Work prep
08:15-08:20	FE -1	Mass Constituents Analyzer (MCA) valve opening
08:15-08:45	CDR	Installation of ATV control panel in ISS SM. Tagup with specialists (S-band)
08:20-08:25		VTR video tape loading
08:25-08:40	FE -1	Set up video equipment for video imagery of exercise with RED
08:40-09:00		IWIS installation
08:45-12:35	CDR	ATV control panel cable routing. Tagup with specialists (S-band)
09:00-09:05		Installation of RSU sensor
09:05-10:35	FE -1	Seal replacement in internal sampler adapter (IFM)
10:35-12:05	F E - I	Physical Exercise (RED)
12:05-13:05		Physical exercise (CEVIS)
12:35-14:05	CDR	Physical Exercise (TVIS), day 3
13:05-13:10		Disconnect RSU sensor
13:10-13:25	FE -1	IWIS removal
14:00-14:05		On MCC Go: ISS repress with O2 from Progress 353 CpΠK (start)
14:05-15:05		LUNCH
15:05-16:35	CDR	Installation and activation of БУАП (Antenna Switching Controller) Tagup with specialists (S-band)
15:05-15:10		ISS O2 repress from Progress 353 CpΠK (end)
15:10-15:30		IMS file prep
15:30-16:00		СОЖ maintenance
16:00-16:05	FE -1	HAM radio setup
16:05-16:15		HAM radio session
16:25-16:40		Clarissa software activation
16:40-17:20		Clarissa s/w training
16:35-17:35	CDR	Physical exercise (VELO + Load Trainer/Cycle 1), day 3
17:20-17:25		Deactivation of Clarissa s/w
17:25-17:30	FE -1	Transfer TVIS, RED, and HRM data to MEC
17:30-18:25		RS cargo setup in USOS before Shuttle arrival
17:35-18:25	CDR	Equipment Search to Flush Condensate Line [MOK]
18:25-18:40	FE -1	Questionnaire - log entry
18:40-18:50		Questionnaire
18:25-18:50	CDR	Daily plan review
18:50-19:05		Daily planning conference (S-band)
19:05-19:30	CDR	Report prep

19:05-19:25	FE -1	
19:25-19:30	L = 1	Daily food prep
19:30-20:00		DINNER
20:00-20:25	FE -1	Daily food prep
20:00-20:30	CDR	
20:25-21:25	FE -1	Pre-sleep
20:30-21:30	CDR	
21:25-21:30	FE -1	Mass Constituents Analyzer (MCA) valve closure
21:30-06:00		SLEEP
Task list	CDR	PLANTS-2. Payload status check

Note: See OSTP for references to US activities. End of radiogram