Radiogram No. 6088u Form 24 for 09/10/07 OUTFITTING СУБА (ППС) [System Power Panel] . КСК 1, 2 [Network Channel Controller] CHECKOUT

| GMT | CREW | ACTIVITY |
|-------------|--------------|---|
| 06:00-06:10 | | Morning Inspection |
| 06:10-06:40 | | Post-sleep |
| 06:40-07:30 | | BREAKFAST |
| 07:30-07:40 | | Prep for Work |
| 07:40-07:55 | | Daily Planning Conference (S-band) |
| 07:55-08:15 | CDR | Prep for Work |
| 07:55-08:00 | FE-1,FE-2 | Prep for Work |
| 08:00-11:00 | FE-1 | FGB СУД Equipment Teardown (СС-16A) |
| 08:00-09:30 | FE-2 | Physical Exercise (TVIS) |
| 08:15-08:25 | CDR | KCK 1, 2 Checkout. Tagup with specialists (S-band) |
| 08:25-08:55 | | PILOT. Setup work site and install sensors. <i>Tagup with specialists</i> (S-band) / r/g 6089 |
| 08:55-10:35 | | PILOT. Experiment ops. Tagup with specialists (S-band) |
| 09:30-10:30 | EE 2 | Physical Exercise (RED) |
| 10:30-12:30 | FE-2 | Unpacking hardware delivered by 13A.1 |
| 10:35-11:15 | CDR | СОЖ Maintenance |
| 11:00-11:30 | FE-1 | SSC - Ping test prep |
| 11:15-12:15 | CDR | Physical Exercise (VELO+RED), day 1 |
| 11:30-11:45 | FF 4 | SSC - Ping test |
| 12:00-13:30 | FE-1 | Physical Exercise (TVIS), day 1 |
| 12:25-12:40 | CDR | VTR tape changeout |
| 12:30-13:30 | FE-2 | Unpacking hardware delivered by Progress 361 |
| 12:45-13:15 | CDR | Flushing БРПК separator |
| 13:15-13:30 | CDR | Activation of Soyuz 220 Gas Analyzer |
| 13:30-14:30 | | LUNCH |
| 14:30-16:30 | CDR | Stowing hardware for disposal in Progress 360 and IMS updates |
| 14:30-15:00 | FE-1 | SSC - Post-Ping test hardware stowage |
| 14:30-14:50 | FE-2 | EXPRESS Laptop Computer Swap |
| 14:50-15:30 | - FE-Z | Download IWIS data |
| 15:00-16:40 | FE-1 | PILOT. Experiment ops. Tagup with specialists (S-band) |
| 15:40-16:00 | FE-2 | EXPRESS Rack Interface Controller Start Software Load |
| 16:30-16:45 | Γ Γ Ζ | Questionnaire - journal entry |
| 16:30-18:00 | CDR | Physical Exercise (TVIS), day 1 |
| 16:40-17:10 | FE-1 | PILOT. Disassemble work site. Tagup with specialists (S-band) |
| 16:45-16:55 | | EXPRESS Rack Interface Controller End Software Load |
| 17:05-17:20 | FE-2 | EVA ratchet wrench inspection |
| 17:20-18:05 | | SAFER Troubleshooting Drill |
| 17:30-18:30 | FE-1 | Physical Exercise (VELO+RED), day 1 |
| 18:00-18:30 | CDR | Counter Measure System (CMS) Harmful Contaminant Measurements in SM |
| 18:05-18:40 | FE-2 | Start BSA battery charge |
| 18:30-18:40 | FE-1 | Evening work prep |

| 18:30-18:35 | CDR | Transfer TVIS/RED/CEVIS/HRM data to MEC |
|--------------------|-----------|---|
| 18:40-18:55 | | PCS R10U OBT |
| 18:55-19:15 | | Evening work prep |
| 19:15-19:30 | | Daily Planning Conference (S-band) |
| 19:30-20:00 | | DINNER |
| 20:00-20:30 | | Daily Food Prep |
| 20:30-21:30 | | Pre-sleep |
| 21:30-06:00 | | SLEEP |
| Task List | CDR | IMS update |
| | FE-1 | GSF-JAXA. ТБУ temperature monitoring (in the morning) |
| Get-Ahead Tasks | FE-1, CDR | ISS RS Audit (behind panels in work areas) |
| | | ISS RS Photo/video |

Note: See OSTP for references to US activities. End of Radiogram