Install and Connect СУБА ИУС WAP

GMT	CREW	ACTIVITY
06:00-06:20	CDR	Blood test using Portable Clinical Blood Analyzer (PCBA)
06:00-06:10	FE-1, FE-2	Morning Inspection
06:10-06:40		Post-sleep
06:20-06:30	CDR	Morning Inspection
06:30-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:50	FE-1 FE-2	Prep for Work
07:30-07:45		
07:30-07:50	CDR	Post-sleep
07:45-07:50	FE-2	JEMRMS. Backup Controller (BUC) power on
07:50-08:05		Daily Planning Conference (S-band)
08:05-08:35	CDR	Prep for Work
	FE-1, FE-2 assistance	Periodic Health Status
08:35-09:05	CDR, FE-2 assistance	T Choule Ficality Status
08:35-08:45		Start RSE2 Laptop Anti-virus update. Tagup with specialists (S-band)
08:45-08:50	FE-1	PHASE. Photo 1 Session 4
08:50-09:25		СОЖ Maintenance
09:05-10:35	FE-2	Physical Exercise (RED)
09:05-09:45	CDR	Periodic Health Status (PHS) Data Entry and Stow Hardware
09:25-09:30	FE-1	Terminate RSE2 Laptop Anti-virus update. Tagup with specialists (S-band)
09:30-10:30		PILLE dosimeter readings, photography of dosimeters
09:45-10:15	CDR	EVA Grease Gun Nozzle Modification
10:15-10:45	CDR	EVA Grease Gun Preparation
10:30-11:30	FE-1	Install and connect СУБА ИУС WAP. Tagup with specialists (S-band)
10:35-11:35	FE-2	Physical Exercise (TVIS)
10:45-11:05	CDB	Re-measure Node 1 Stbd Aft IMV after fan cleaning.
11:05-11:20	CDR	Duxseal ISS audit
11.20 12.00	FE-1	Physical Exercise (TVIS), day 3
11:30-13:00	CDR	Physical Exercise (RED)
11:35-12:05	FE-2	DOUG SW review
12:05-12:10		JEMRMS. Backup Controller (BUC) power off
12:10-13:15	FE-2	JPM - terminate vestibule depress
13:00-14:00	CDR, FE-1 FE-2	LUNCH
13:15-14:15		
14:00-14:05	FE-1	PHASE. Photo 2 Session 4
14:00-14:15	CDR	Set up video equipment for ARED exercise video

14:05-14:15	FE-1	PLANTS-1. Data Collection Start
14:15-15:30	FE-2	JPM/JLP - jumper-hose installation after vestibule leak check
14:15-15:45	FE-1	Install and connect СУБА ИУС WAP, test. Tagup with specialists (S-band)
14:15-14:25	CDR	CWC Audit
14:25-14:30		EXPRESS Rack 6 Potable Water Dispenser Flush
14:40-17:10		ARED activation and checkout Part 1
15:45-15:55	FE-1	PLANTS-1. Complete data collection and downlink data
15:55-16:15		Pre-pack Laptop TP2 for disposal
16:00-17:10	FE-2	ARED activation and checkout Part 1
16:15-17:15	FE-1	Physical Exercise (VELO), day 3
17:10-17:20	CDR	Disposal of Glacier desiccant packages
17:15-17:55	FE-1	Replacement of separator in БРПК-2 (Condensate Separation and Pumping Unit). <i>Install</i> # 405006 delivered on Progress 401 (00034864, ΦΓБ1ΠΓΟ_1_112_1)
17:20-17:25	CDR	Stow video equipment used for ARED exercise video
17:30-18:30		Physical Exercise (TVIS)
17:30-17:40	FE-2	PAO Hardware Setup
17:40-17:50		Crew Prep for PAO
17:50-18:10		PAO Event (Ku + S-band)
17:55-18:15	FE-1	IMS Update
18:10-18:15	FE-2	PAO Hardware Deactivation
18:15-18:45	FE-1	Evening Work Prep
	FE-2	Skills training for the Shuttle R-Bar Pitch Maneuver
18:35-18:40	CDR	VTR swapout.
18:45-19:00		Daily Planning Conference (S-band)
19:00-19:05	CDR	Glacier status check
	FE-1	PHASE. Photo 3 Session 4
	FE-2	Image downlink
19:05-19:30		Evening Work Prep
19:30-21:30		Presleep (dinner, daily food prep, evening toilet)
21:30-06:00		SLEEP

- Notes:

 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC / r/g 6083, 6004

 2. See OSTP for references to US activities.
 End of Radiogram