## MPLM Berthing

GMT	Crew	Activity
12:20–14:20	CDR-4 FE-2-4	Post-sleep
12:20–15:20		
12:20–14:35	FE-1-4	
12:50–14:10	ISS3	Personal hygiene (post-sleep)
14:10–14:25		Daily planning conference (S-band)
14:20–14:35	CDR-4	Private medical conference (S-band)
14:35–15:05		Post-sleep
14:25–14:35	ISS3	Personal hygiene (post-sleep)
14:35–14:50	FE-1 PLT	Work prep
14:35–15:20		
14:35–14:50	FE-1-4	Seat liner prep
14:50–15:20	CDR	CBM setup for berthing
14:50–15:20	FE-1	IMS conference (S-band)
15:05–15:20	CDR-4	Seat liner prep
15:20–18:10	CDR-4	Seat liner installation and checkout
15:20–17:20	FE-1, FE-1-4	
15:20–15:25	CDR	???S deactivation
15:20–18:10	PLT	Seat liner installation and checkout
15:45–16:05	FE-2-4	SOKOL prep on Middeck
16:05–16:20	FE-2-4	Seat liner prep
16:20–18:10	FE-2-4, CDR	Seat liner installation and checkout
17:20–17:50	FE-1	Seat liner temp stow
17:25–17:30	FE-1-4	NODE1 Nadir CBM checkout
18:10–18:40	CDR, PLT	Seat liner temp stow
18:10–19:10	CDR-4	Transfer ops
18:10–18:30	FE-2-4	Entry suit leak check
18:20–18:50	FE-1	Transfer ops
18:20–18:25	FE-1-4	CBM ops (part 1)
18:30–18:45	FE-2-4	Entry suit dryout
18:30–18:35	FE-1-4	CBM ops (part 2)
18:40–18:55	FE-1-4	CBM bolt capture
18:40–19:40	PLT	Physical exercise (TVIS)
18:45–19:10	FE-2-4	EXPRESS Rack4 prep
18:50–19:30	FE-1	Maintenance of ???
18:55–19:25	CDR, FE-1-4	???S removal
19:10–20:10	FE-2-4	Transfer of powered payload STES 010 from STS to ISS
19:25–19:55	FE-1-4	
19:30–20:30	FE-1	MEAL
19:40–20:40	CDR, PLT	]
19:55–20:55	FE-1-4	MPLM/NODE1 vestibule repress
20:10–20:30	CDR-4	Entry suit leak check
1		

20:10–20:40	FE-2-4	MDDK PREP PWR
	FE-1	Transfer ops
20:30–22:25	CDR-4	Entry suit dryout
	PLT	ISS-to-Middeck transfer
20:40–21:40	CDR	ISS-to-Middeck transfer
20:40–21:40	FE-2-4	133-to-ivilidaeck transier
20:45–21:45	CDR-4	MEAL
20:55–21:15	FE-1-4	Entry quit look abook
21:15–21:30		Entry suit leak check Entry suit dryout
21:30–00:40	FE-1-4	NODE 1/MPLM vestibule outfit
	CDR	
21:40–22:30	1 -	Transfer ops
21:40–21:50	FE-2-4	STES 010 installation
21:40–22:40	PLT	Transfer ops
21:45–22:30	CDR-4	DTE0 040
21:50–22:20	FE-2-4	STES 010 activation
22:20–22:40		Payload status check
22:25–00:25	FE-1	Physical exercise (TVIS)
22:30–22:45	CDR, CDR-4	PAO event (S-band)
22:40–23:55	FE-2-4	Transfer ops
22:45–00:45	CDR	Physical exercise (CEVIS)
22:55–23:20	PLT	MPLM activation (part 1)
23:15–23:25	CDR-4	Entry suit gloves dryout
23:20–23:55	PLT	Transfer ops
23:25–00:35	CDR-4	
23:55-00:00	FE-2-4	Entry suit gloves dryout
23:55–00:10	PLT	MPLM activation (part 2)
00:00-00:55	FE-2-4	Transfer ops
00:10-01:10	PLT	Physical exercise (TVIS)
00:25-00:55	FE-1	??21 INGRESS
00:35-01:05	CDR-4	Report prep
00:40-02:10	FE-1-4	MPLM prep for transfer
00:55–01:10	FE-2-4	EXPRESS Rack 1: laptop powerup
	FE-1, CDR	MPLM ingress
01:10-01:25	FE-1	Collection of air samples with ??-1? sampler
01:15-01:35	CDR-4, FE-2-4	Entry suit stowage
01:25-04:20	ISS3	Pre-sleep
01:35-02:05	CDR-4, FE-2-4	Report prep
02:05-02:20	ISS4	Daily planning conference (S-band)
02:20-02:35	FE-1-4, FE-2-4	Private medical conference (S-band)
02:35–04:20		Personal hygiene (pre-sleep)
04:20–12:50	ISS4	
	ISS3	SLEEP
	TD for reference	. 110 - 41 141

Note: See OSTP for references to US activities

## Crewmember designations:

ISS3 - FE-1, CDR, PLT

ISS4 - FE-1-4, FE-2-4, CDR-4

End of radiogram