REMOVING PCE Z0000 BOX FROM SM

GMT	CREW	
06:00-06:10		Morning Inspection
06:10-06:40		Post-sleep
	FE-2	1 ost sloop
	CDR,FE-1	BREAKFAST
	CDR,FE-1	Prep for Work
07:45-08:00	ODIX,I L-I	Daily Planning Conference (S-band)
	FE-1	Daily Flatilling Conference (S-barid)
	FE-2	Prep for Work
08.00-08.20	F L - Z	Removing PCE Z0000 Box from SM.
08:15-12:15	FE-1	Tagup as necessary (S-band)
08:20-08:30	FE-2	TOCA Water Analysis
08:20-11:30	CDR	SDTO Component Repair Experiment 1
08:30-10:00	FE-2	Physical Exercise (ARED)
10:00-11:00	FE-2	Physical Exercise (CEVIS)
11:45-11:55	FE-2	TOCA 2 Data Recording
11:45-13:15	CDR	Physical Exercise (ARED)
11:55-12:20	FE-2	CSA O2 Analyzer Calibration
12:15-13:15	FE-1	Physical Exercise (VELO), day 2
13:15-14:15		LUNCH
14:15-15:15	FE-1	Removal of Antenna Switch Box (БУАП) from SM. <i>Tagup as necessary (S-band)</i>
14:30-14:35	CDR	HAM Radio Setup
14:35-14:45	CDR	HAM Radio Session
15:15-15:45	FE-1	Return SM panels 225 and 226 to initial configuration after PCE hardware removal
15:15-17:40	CDR	SDTO Component Repair Experiment 1
15:30-16:30	FE-2	EXPRESS Rack 5 Pinout Test
15:45-16:25	FE-1	СОЖ Maintenance
16:25-17:55	FE-1	Physical Exercise (TVIS), day 2
16:40-17:55	FE-2	Cleaning ventilation grilles on FGB interior panels (201, 301, 401), FGB ЦВ2 fan grill
17:40-18:40	CDR	Physical Exercise (TVIS)
17:55-18:05	FE-1	IZGIB (BEND)-DAKON. Hardware Test – Start. Tagup with specialists (Sband)
17:55-18:15	FE-2	IMS Update
18:05-18:45	FE-1	Evening Work Prep
18:15-18:45	FE-2	
18:45-19:00		Daily Planning Conference (S-band)
19:00-19:30	CDR,FE-2	Evening Work Prep
19:00-19:10	FE-1	IZGIB (BEND)-DAKON. Hardware Test – Terminate. <i>Tagup with specialists</i> (S-band)
19:10-19:30	FE-1	Evening Work Prep

19:30-21:20	FE-1	Presleep (dinner, daily food prep, evening toilet)
19:30-21:30	CDR,FE-2	
21:20-21:30	FE-1	SONOCARD. Experiment Run Start
21:30-06:00		SLEEP

- Notes:
 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC
 2. See OSTP for references to US activities.
 End of Radiogram